

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT SEDGWICK SINGAPORE PTE. LTD Ref: CS3/SGK23000169/Rwy3e2 30 CECIL STREET, LEVEL 12 Date: 07/03/2023 PRUDENTIAL TOWER SINGAPORE 049712 SGK Code: Policy Particulars :- (THIRD PARTY CLAIM) 1. Insured Veh. **FORKLIFT** XD 2853L Veh. Inspected 0.00 Policy No. Coverage (\$) 6018297/ARI 0.00 Claim No. Excess (\$) RAJADURAI ABRAHAM 05/01/2023 **Assign Date** Assign From 2. **Vehicle Particulars & Condition** MITSUBISHI FP51JDR4RDEA 12882 Make & Model **HIDDEN** 2008 Engine No. Year of Reg. FP51JDA00618 WHITE Chassis No. Colour Odometer 39305 KM IN ORDER Steering **IN ORDER** NIL Modification **Brakes** FAIR General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 295/80 R22.5 **ROADONE** 8 mm L/H Front Tyre 295/80 R22.5 ROADONE 8 mm 295/80 R22.5 (D) **ROADONE** 8/8 mm R/H Rear Tyre L/H Rear Tyre 295/80 R22.5 (D) **ROADONE** 8/8 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 19/11/2022 Inspect Date / Time 06/01/2023 (11:04 AM) **Accident Date** Survey held at Sincere Garage Pte Ltd 48 Toh Guan Road, #02-126 Enterprise Hub, S608586 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$11,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/SGK23000169/Rwy3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

8 Working Days

**REGD Auto Consultant-SAE, Licensed Appraiser**