



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|--|--------------------|
| MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581 | | Ref: CS/FCI23000171/Kvy3m4 Date: 23/03/2023 Code: FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SBS 6523U | Veh. Inspected | SKN 3588Y |
| Policy No. | D-22099843MFBP | Coverage (\$) | 0.00 |
| Claim No. | D23000084MFBP | Excess (\$) | 0.00 |
| Assign From | HARMINDER KAUR | Assign Date | 05/01/2023 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA AXIO X (A) | c.c | 1496 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | NZE1416071683 | Colour | METALLIC SILVER |
| Odometer | 273151 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 185/60 R14 | MICHELIN | 4 mm |
| L/H Front Tyre | 185/60 R14 | MICHELIN | 4 mm |
| R/H Rear Tyre | 185/60 R14 | CST | 2 mm |
| L/H Rear Tyre | 185/60 R14 | CST | 2 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 30/12/2022 | Inspection Date | 11/01/2023 |
| Survey held at | AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 | | |
| 5a. Remarks | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 7 Working Days | |