

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000177/AYA3Q2**Date:** 17/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263118-01
Claimant Vehicle No :	SMA7537M	Insured Vehicle No :	SMR2956E
Date of Loss:	19/12/2022	Nature of Claim:	TP
		Claim No:	8768971537SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA7537M	Engine No:	L15B5552773
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11302766
Reg. Date:	19/06/2018 (Man. Year: 2018)	Odometer:	92790 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,063.68	5,854.64	4,209.04	41.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,120.00	2,070.00	3,050.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,183.68	7,924.64	7,259.04	47.81
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	15,183.68	6,300.00	8,883.68	58.51
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		6,806.75		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment:	20/12/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	20/12/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	865.50 FL	*745.00 FL
2	1		*REAR BUMPER REFLECTOR	N/S Cracked	302.20 FL	*151.10 FL
3	1		*REAR BUMPER SIDE	N/S Deformed	460.00 FL	*230.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	114.00 FL	*70.00 FL
5	1		*TAIL LAMP	N/S Cut	950.00 FL	*475.00 FL
6	1		*TAILGATE	Dented	1,420.00 FL	*1,100.00 FL
7	1		*TAILGATE LOGO	Not Necessary	65.00 FL	*- FL
8	1		*TAILGATE EMBLEM VEZEL	Necessary	68.00 FL	*68.00 FL
9	1		*TAILGATE OUTER GARNISH	Cracked	220.00 FL	*220.00 FL
10	2		*TAILGATE SIDE LAMP	N/S Cut / O/S Cracked	480.00 FL	*480.00 FL
11	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
12	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
13	1		*TAILGATE TOP LOCK	Damaged	180.00 FL	*180.00 FL
14	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
15	1		*TAILGATE INNER TRIM	Cracked	398.60 FL	*398.60 FL
16	1		*TAILGATE WEATHERSTRIP	Cut	168.40 FL	*168.40 FL
17	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
18	1		*TAILGATE LOCK CONNECTOR	Not Necessary	379.00 FL	*- FL
19	1		*BUZZER	Not Necessary	109.00 FL	*- FL
20	1		*REAR FENDER INNER TRIM	N/S Cracked	798.20 FL	*325.00 FL
21	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
22	2		*REAR FENDER ARCED GARNISH	Not Necessary	369.40 FL	*- FL
23	1		*REAR END PANEL	Dented	530.00 FL	*530.00 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	146.30 FL	*146.30 FL
25	1		*REAR FLOOR PANEL BOTTOM GARNISH	Deformed	269.00 FL	*269.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Deformed	300.40 FL	*300.40 FL
27	1		*REAR STORAGE BOX	Cracked	495.00 FL	*385.00 FL
28	1		*REAR NUMBER PLATE	Bent	80.00 FS	*50.00 FS
29	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
30	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*10.00 FS
31	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
32	1		*SET TAILGATE INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
35	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
36	1		*SET REAR FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
37	1		*SET REAR FENDER ARCED GARNISH CLIP	Not Necessary	80.00 FS	*- FS
38	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*10.00 FS
39	1		*REAR END PANEL TOP GARNISH CHROME (SPECAIL TYPE)	Necessary	250.00 FS	*180.00 FS
40	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
41	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
42	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
43	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
44	1		*SET REVERSE LAMP (LED) (SPECAIL TYPE)	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,997.10	7,135.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,933.42	1,281.16
Total Parts (\$)	10,063.68	5,854.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	60.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	New	80.00	50.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
10	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			5,120.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >