

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23000187/DNY3M4**Date:** 15/06/2023**REFERENCE****Insured/Claimant:** MUHAMMAD EKRAM BIN AZIMULLAH**Policy No:** SP2003542790**Date of Loss:** 12/12/2022**Nature of Claim:** OD**Claim No:** 202222008826/FR**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SJA1161M**Make & Model:** MERCEDES-BENZ E250, 1.8 (A)**Engine No:** 27186030007944**Reg. Date:** 30/11/2009 (Man. Year: 2009)**Chassis No:** WDD2120472A094871**Colour:** Grey**Odometer:** 351360 km**Engine Capacity:** 1796 cc**Market Value/New Car Price:** S\$85,000.00**Sum Insured (\$\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 245/40 R18**Rear Tyre Size:** 245/40 R18**Front Left Side:** Nexen 5 mm**Rear Left Side:** Nexen 5 mm**Front Right Side:** Nexen 5 mm**Rear Right Side:** Nexen 5 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,196.40	2,693.90	2,502.50	48.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	730.00	440.00	37.61
Paintwork Labour	1,330.00	800.00	530.00	39.85
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,696.40	4,223.90	3,472.50	45.12
- Excess (\$\$)	0.00	1,100.00	-1,100.00	
(\$\$)	7,696.40	3,123.90	4,572.50	59.41
+ GST 8.00/8.00% (\$\$)	615.71	249.91	365.80	59.41
Nett Amount (\$\$)	8,312.11	3,373.81	4,938.30	59.41

INSPECTION**Date of Assignment:** 06/01/2023 **Present Location:**

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 10/01/2023 **Inspected At:**

Kan Fook Sing Motor Workshop (Defu)

Blk 8 JTC Defu Industrial City

#04-29 Defu South Street 1, Singapore 533758

Estimated Period of Repair: 3.0 days**Adjuster:** BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2023)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA1161M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER (WCP)	Repair	1,480.00 F	*- F
2	1		*REAR BOOT REFLECTOR RH (WCP)	Not Necessary	220.00 F	*- F
3	1		*REAR BOOT HINGE RH (WCP)	Not Necessary	320.00 F	*- F
4	1		*REAR LAMP RH (WCP)	Cracked	380.00 F	*455.00 F
5	1		*REAR BUMPER (WCP)	Torn	779.00 F	*770.00 F
6	1		*REAR BUMPER CHROME RH (WCP)	Broken	78.00 F	*78.00 F
7	1		*REAR BUMPER CHROME LH (WCP)	Necessary	78.00 F	*78.00 F
8	1		*REAR BUMPER CEHROME CENTRE (WCP)	Broken	90.00 F	*90.00 F
9	2		*REAR BUMPER SENSOR (WCP)	Damaged	296.00 F	*148.00 F
10	4		*REAR BUMPER SENSOR RING (WCP)	Not Necessary	32.00 F	*- F
11	1		*REAR BUMPER SENSOR WIRE (WCP)	Not Necessary	88.00 F	*- F
12	1		*REAR BUMPER TOW COVER (WCP)	Not Necessary	40.00 F	*- F
13	1		*REAR BUMPER SIDE RETAINER RH (WCP)	Serviceable	23.00 F	*- F
14	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	450.00 F	*460.00 F
15	10		*REAR BUMPER CLIP (WCP)	Necessary	50.00 F	*50.00 F
Supplementary #1						
16	1		*TAIL LAMP LOWER SUPPORT RH (WCP)	Broken	45.00 F	*45.00 F
17	1		*TAIL LAMP LOWER SUPPORT LH (WCP)	Broken	45.00 F	*45.00 F
18	1		*BOOT LID INNER LOCK (WCP)	Bent	230.00 F	*230.00 F

F=Franchise part.

Sub Total (S\$)	4,724.00	2,449.00
+ Margin on L,N Items 10.00/10.00% (S\$)	472.40	244.90
Total Parts (S\$)	5,196.40	2,693.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	780.00	500.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	620.00	500.00
<u>Supplementary #1</u>				
<u>Paintwork Labour</u>				
4	SPRAYPAINTING CHARGES (REAR END PANEL & REAR FENDER)	New	550.00	300.00
<u>Labour Items</u>				
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR END PANEL & REAR FENDER)	New	500.00	200.00
Gross Labour Cost (\$\$)			2,500.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >