

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1063G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
10	CLIPS PIECE, FRT & RR BUMPER @\$4.80 (DISC 25%)	NECESSARY	48.00	36.00
2	PAD, RR BUMPER, RH & LH , 1 @\$4.30	NOT NECESSARY	8.60	-
2	PAD, RR BUMPER, RH & LH , 2 @\$4.30	NOT NECESSARY	8.60	-
2	PAD, RR BUMPER, RH & LH , 3 @\$4.30	NOT NECESSARY	8.60	-
3	PAD, RR BUMPER, CTR @\$2.50	NOT NECESSARY	7.50	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	127.40	-
1	SEAL, RR BUMPER , RH	NOT NECESSARY	95.50	-
1	GUARD, RR BUMPER, LOWER	NOT NECESSARY	623.50	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	PATCH, SIDE PANEL REAR END , RH & LH	NOT NECESSARY	37.70	-
1	LINER, REAR FENDER , RH	NOT NECESSARY	151.10	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	478.90	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR SEE LABOUR	943.10	-
			2,718.50	36.00
	<u>LABOUR</u>			
	PANEL BEATING AND BODY WORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY AND PANEL SUB-ASSY, FENDER REAR RH.		676.00	300.00
	SPRAY PAINT.		756.00	400.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			1,932.00	700.00
	GRAND TOTAL		4,650.50	736.00

Report Ref No. NS/INC23000188/Twp3m4





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		600.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23000188/Twp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.