

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 2571B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED	1,250.00	1,050.00
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	18.70	18.70
1	FRONT BUMPER SIDE GARNISH RH	SERVICEABLE	198.00	-
1	HEADLAMP RH	SERVICEABLE	2,598.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	411.90	-
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	145.00	-
1	FRONT FENDER INNER EMBLEM RH	NOT NECESSARY	42.00	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	398.00	-
1	FRONT KNUCKLE ARM BEARING RH	SERVICEABLE	215.00	-
1	FRONT LOWER ARM RH	SERVICEABLE	548.00	-
	LESS 20% DISCOUNT		-1,164.92	-213.74
			4,659.68	854.96
	SPECIAL NETT ITEMS			
1	FRONT WHEEL HUB CAP RH (SN)	SERVICEABLE	80.00	-
1	FRONT RIM RH (SN)	SERVICEABLE	350.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	60.00
			510.00	60.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL WIRING.	NOT NECESSARY	80.00	-
	REMOVE AND RENEW FORNT UNDERCARRIAGE. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.	NOT NECESSARY	400.00	-
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	15.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	300.00	-
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	200.00
	PANEL BEATING ON AFFECTED AREAS.		600.00	200.00
			2,195.00	400.00
	GRAND TOTAL		7,364.68	1,314.96

Report Ref No. CS/LIP23000189/Kny3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,050.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LIP23000189/Kny3e2

MARKET VALUE: \$99,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$34,837.00=NETT VALUE: \$64,163.00

KONG SENG CHEONG

Licensed Appraiser