7/4/23, 10:13 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG23000193/UPA3Q2

04/07/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800147871 **Claimant Vehicle** YM1667E Insured Vehicle No: **GBH1214C** 

No:

Date of Loss: 04/01/2023 Nature of Claim: TP Claim No: 3846521435SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: YM1667E

Make & Model: ISUZU FSR, 8.2 D 33P (M) 6HH1410199 Engine No:

Reg. Date: 10/11/2005 (Man. Year: 2005) Chassis No: JALFSR33P57000054

Colour: White Odometer: 495689 km

**Engine Capacity:** 8226 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Nο Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 8.25 R20 Rear Tyre Size: 8.25 R20 (D) Front Left Side: TAITONG 6 mm Rear Left Side: TAITONG 6/6 mm Front Right Side: TAITONG 6 mm Rear Right Side: TAITONG 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,806.00	2,200.00	36,606.00	94.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	300.00	5,550.00	94.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,656.00	2,500.00	42,156.00	94.40
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	44,656.00	2,000.00	42,656.00	95.52
+ Loss of Use (2.0 x S\$	100.00/day) (S\$)	200.00		
+ Doc/	Search Fee (S\$)	26.75		
N	lett Liability (S\$)	2,226.75		
Global Sum	Settlement (S\$)	2,220.00		

**INSPECTION** 

Date Inspected:

Date of Assignment: 06/01/2023

SPEEDWERKZ PTE LTD (HQ)

1 Kaki Bukit Ave 6 09/01/2023 Inspected At:

#01-73 Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: **CHEW HSIAO TONG** 

## **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILLAMP (CRACKED)	Not Consistent With The Impact	690.00 FL	*- FL
2	1	*REAR NUMBER PLATE LIGHT	Not Necessary	75.00 FL	*- FL
3	1	*REAR TAIL LAMP BRACKET	Not Necessary	130.00 FL	*- FL
4	1	*REAR NUMBER PLATE BASE	Not Necessary	145.00 FL	*- FL
5	2	*REAR 60 KM STICKER	Not Necessary	50.00 FL	*- FL
6	2	*UNDER CHASSIS BEAM	Not Necessary	2,600.00 FS	*-FS
7	1	*REAR LIFT GATE PLATFORM ASSY	Not Necessary	1,150.00 FS	*- FS
8	1	*REAR LIFT GATE O/S LIFTING CYLINDER	Not Necessary	4,500.00 FS	*-FS
9	1	*REAR LIFT GATE N/S LIFTING CYLINDER	Damaged / Leaking	4,500.00 FS	*2,200.00 FS
10	1	*REAR LIFT GATE O/S LIFTING CYLINDER INNER	Not Necessary	3,800.00 FS	*-FS
11	1	*REAR LIFT GATE N/S LIFTING CYLINDER INNER	Not Necessary	3,800.00 FS	*-FS
12	1	*REAR LIFT GATE MOUNT ARM ASSY	Repair	3,500.00 FS	*-FS
13	1	*REAR LIFT GATE TRACK FRAME ASSY	Not Necessary	5,500.00 FS	*- FS
14	4	*REAR LIFT GATE HYDRAULIC HOSE	Not Necessary	2,200.00 FS	*-FS
15	1	*REAR LIFT GATE HYDRAULIC OIL	Not Necessary	250.00 FS	*- FS
16	1	*REAR BUMPER (BENT)	Not Consistent With The Impact	750.00 FS	*-FS
17	1	*APPLE REAR SAFETY STICKER	Not Necessary	80.00 FS	*-FS
18	1	*REAR POWER GATE MAIN CONTROL WITH BOX	Not Necessary	4,500.00 FS	*-FS
19	1	*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
20	1	*REAR WOODEN CROSS BEAM	Not Necessary	650.00 FS	*-FS
F=Fra	nchise	part. S=SpcNett. L=ListItemDisc.	Sub Total (S\$)	38,915.00	2,200.00

 Sub Total (\$\$)
 38,915.00
 2,200.00

 - List Item Discount on L Items 10.00/10.00% (\$\$)
 109.00
 0.00

Total Parts (S\$) 38,806.00 2,200.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX REAR CARRIER	New	550.00	0.00
2	REMOVE & REFIX REAR DAMAGED PARTS INCLUDING REINSTATEMENT OF THE NECE AND FITTING TO FACILITATE REPAIRS, JAC, PANEL BEAT, RESHAPE THE EFFECTED PA, CORRECT AND REALIGN THE NECESSARY	ESSARY ATTACHMENTS CK UP ,STRAIGHTEN RTS AND COMPONENTS	4,500.00	300.00
3	RESPRAY PAINTING	New	800.00	0.00
		Gross Labour Cost (S\$)	5,850.00	300.00
	Report v	vas unsubmitted during this print-out.		

< END OF ESTIMATES >