



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 549B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
10	BUMPER CLIP	NECESSARY	12.00	12.00
1	COVER-FR BUMPER	SCRATCHED	481.10	481.10
1	MOULDING-FRONT BUMPER CTR,UPR	NOT NECESSARY	138.30	-
1	MOULDING-FRONT BUMPER,RH	SCRATCHED	93.00	93.00
1	LAMP ASSY-DAY RUNNING LIGHT,RH	NOT NECESSARY	642.50	-
1	BRACKET-FR BUMPER SIDE SUPT,RH	NOT NECESSARY	12.00	-
1	BRACKET-FR BUMPER SIDE,RH	NOT NECESSARY	28.00	-
1	LAMP ASSY-HEAD,RH	CRACKED	2,110.30	2,110.30
	LESS 20% DISCOUNT		-703.44	-539.28
			2,813.76	2,157.12
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
			40.00	-
	<u>LABOUR</u>			
	TO CARRY OUT ACCIDENT BODY REPAIR.		840.00	420.00
	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		760.00	510.00
			1,600.00	930.00
	GRAND TOTAL		4,453.76	3,087.12
	RECOMMENDED COST OF REPAIRS			3,087.12

Report Ref No. CS/SMR23000195/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.