

ASS. REC. BY:

REF:

A15/23000199/KCP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Accord

of _____ 488

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 879k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMS 6202R Yr Regn: 03, 20Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz c.c. 1318Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 43922 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHMGK 3850 LS 217660Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: P mm Rear: P mmR/Bal. P mm R/Bal. P mmL/Bal. P mm L/Bal. P mmD.O.A. 1/1/23 D.O.I. 10/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1) 16/1/21 PM @ 2600d Car

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

TP INSURER:
SHIOGAI SHIOMI

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/01/2023
Vehicle Reg. No.:	SMS6202R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	SHIOGAI SHIOMI		
Make/Model:	HONDA JAZZ, 1.3 CVT (A)	Vehicle Reg. Date:	05/03/2020
Vehicle Colour:	GREY		
Engine No:	L13B15000501	Chassis No:	JHMGK3850LS217660
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	<i>8-5 days</i>		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

Not Notified After Repairing 11 Lm \$2600/p

COST OF CLAIMS

	Amount
Parts	2,413.40
Miscellaneous Items	630.00
Labour	3,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,963.40
+ GST 8.00% (\$\$)	557.07
Nett Amount (\$\$)	7,520.47

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2023)

Parts: 144 HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS6202R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TAIL GATE	0.00	0.00	Ry *380.00 F ✓
2	1		*RAR TAIL GATE ABSORBER LH & RH	0.00	0.00	Sm *160.00 F X
3	1		*REAR TAIL GATE LOGO	0.00	0.00	Me *10.00 F ✓
4	1		*REAR TAIL GATE LOGO JAZZ	0.00	0.00	Me *10.00 F ✓
5	1		*REAR TAIL GATE LOCK	0.00	0.00	Del *65.00 F ✓
6	1		*REAR TAIL GATE INNER TRIM BOARD	0.00	0.00	Sm *60.00 F X
7	1		*REAR TAIL GATE WEATHERSHIELD	0.00	0.00	Dis *40.00 F ✓
8	1		*REAR TAIL GATE LAMP LH	0.00	0.00	Sm *65.00 F X
9	1		*REAR TAIL GATE LAMP RH	0.00	0.00	Sm *65.00 F X
10	1		*REAR LAMP RH	0.00	0.00	St *175.00 F ✓
11	1		*REAR LAMP LOWER BRACKET RH	0.00	0.00	Sm *50.00 F X
12	1		*REAR LAMP LH	0.00	0.00	cmf *175.00 F ✓
13	1		*REAR LAMP LOWER BRACKET LH	0.00	0.00	Sm *50.00 F X
14	1		*REAR BUMPER	0.00	0.00	Ry *180.00 F ✓
15	1		*REAR BUMPER SIDE RETAINER RH	0.00	0.00	Sm *12.00 F X
16	1		*REAR BUMPER SIDE RETAINER LH	0.00	0.00	Sm *12.00 F X
17	1		*REAR BUMPER COVER RH	0.00	0.00	Sm *20.00 F X
18	1		*REAR BUMPER COVER LH	0.00	0.00	Sm *20.00 F X
19	1		*REAR BUMPER CENTRE GARNISH	0.00	0.00	Sm *40.00 F X
20	1		*REAR END PANEL	0.00	0.00	Ry *220.00 F ✓
21	1		*REAR END PANEL TOP GARNISH	0.00	0.00	mgp *35.00 F ✓
22	1		*REAR SPARE TYRE TRIM BOARD	0.00	0.00	Sm *130.00 F X
23	1		*REAR TAILGATE GLASS MOULDING	0.00	0.00	Me *60.00 F ✓
24	1		*REAR WIPER ARM	0.00	0.00	Sm *30.00 F X
25	1		*REAR WIPER MOTOR	0.00	0.00	Sm *130.00 F X

F=Franchise part.

Sub Total (\$\$) **2,194.00**

+ Margin on L,N Items 10.00% (\$\$) **219.40**

Total Parts (\$\$) 2,413.40

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	CAR PLATE NUMBER WITH HOLDER	50.00 X
2	1	REAR BUMPER CLIPS	35.00 —
3	1	REAR END PANEL GARNISH CLIPS	30.00 —
4	1	REAR FENDER INNER SHIELD CLIPS LH & RH	80.00 X
5	1	REAR TAILGATE TRIM BOARD CLIPS	35.00 ✓
6	1	REVERSE SENSOR SET	320.00
7	1	SEALANT	80.00
Sub Total (S\$)			630.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,500.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	120.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00
5	TO REMOVE/RELACE/REFIX TAIL GATE COMPARTMENT, MECHISM TO NEW TAILGATE	New	150.00
6	TO REMOVE/REFIX/REPLACE REAR WINDSCREEN TO NEW TAILGATE	New	150.00
7	TO REMOMVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	New	180.00
8	TO REMOVE/REFIX REVERSE CAMERA	New	100.00
9	TO REMOVE/REPLACE/REFIX REAR REVERSE SENSOR	New	100.00
Gross Labour Cost (S\$)			3,920.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >