

ASS. REC. BY:

REF:

A15/23000199/KCP

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Accord

of

488

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 879K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Soon: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lump Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMS 6202RYr Regn: 03, 20Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz

c.c.

1318

Colour: m. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 43922

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK 3850LS 217660Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rlm / STD / A/Rlm orTyre Size: F: 175/85R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. P mm

Rear

R/Bal. P mmL/Bal. P mmL/Bal. P mmD.O.A. 17/1/23D.O.I. 10/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/1/21 Pm @ 2600d Cntr

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Transportation

\$ - RS, SI

Parking

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

Accord Auto Services Pte Ltd (Co.Reg.No.201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

P INSURER:
SHIOGAI SHIOMI**Allianz Insurance Singapore Pte. Ltd. (HQ)**

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/01/2023
Vehicle Reg. No.:	SMS6202R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	SHIOGAI SHIOMI		
Make/Model:	HONDA JAZZ, 1.3 CVT (A)	Vehicle Reg. Date:	05/03/2020
Vehicle Colour:	GREY		
Engine No:	L13B15000501	Chassis No:	JHMGK3850LS217660
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8-5 days		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

*Not with claim
After
Repairing
61 Lm \$2600p*

COST OF CLAIMS

	Amount
Parts	2,413.40
Miscellaneous Items	630.00
Labour	3,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,963.40
+ GST 8.00% (\$\$)	557.07
Nett Amount (\$\$)	7,520.47

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Source: MRM-SG

Version: 1.0 (Last Synchronised: 04 Jan 2023)

: 144

HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)

ur: Repairer's

(Price-denominated Standard List)

: Code: (Unsubmitted, no print-code for SMS6202R)

ility: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

ther Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*REAR TAIL GATE	0.00	0.00	Ry *380.00 F ✓
1		*RAR TAIL GATE ABSORBER LH & RH	0.00	0.00	Sm *160.00 F X
1		*REAR TAIL GATE LOGO	0.00	0.00	Ma *10.00 F ✓
1		*REAR TAIL GATE LOGO JAZZ	0.00	0.00	Ma *10.00 F ✓
1		*REAR TAIL GATE LOCK	0.00	0.00	Red *65.00 F ✓
1		*REAR TAIL GATE INNER TRIM BOARD	0.00	0.00	Sm *60.00 F X
1		*REAR TAIL GATE WEATHERSHIELD	0.00	0.00	D.Y. *40.00 F ✓
1		*REAR TAIL GATE LAMP LH	0.00	0.00	Sm *65.00 F X
1		*REAR TAIL GATE LAMP RH	0.00	0.00	Sm *65.00 F X
1		*REAR LAMP RH	0.00	0.00	RY *175.00 F ✓
1		*REAR LAMP LOWER BRACKET RH	0.00	0.00	Sm *50.00 F X
1		*REAR LAMP LH	0.00	0.00	CMF *175.00 F ✓
1		*REAR LAMP LOWER BRACKET LH	0.00	0.00	Sm *50.00 F X
1		*REAR BUMPER	0.00	0.00	Ry *180.00 F ✓
1		*REAR BUMPER SIDE RETAINER RH	0.00	0.00	Sm *12.00 F X
1		*REAR BUMPER SIDE RETAINER LH	0.00	0.00	Sm *12.00 F X
1		*REAR BUMPER COVER RH	0.00	0.00	Sm *20.00 F X
1		*REAR BUMPER COVER LH	0.00	0.00	Sm *20.00 F X
1		*REAR BUMPER CENTRE GARNISH	0.00	0.00	Sm *40.00 F X
1		*REAR END PANEL	0.00	0.00	Ry *220.00 F ✓
1		*REAR END PANEL TOP GARNISH	0.00	0.00	mgp.1 *35.00 F ✓
1		*REAR SPARE TYRE TRIM BOARD	0.00	0.00	Sm *130.00 F X
1		*REAR TAILGATE GLASS MOULDING	0.00	0.00	Ma *60.00 F ✓
1		*REAR WIPER ARM	0.00	0.00	Sm *30.00 F X
1		*REAR WIPER MOTOR	0.00	0.00	Sm *130.00 F X

F=Franchise part.

Sub Total (S\$)	2,194.00
+ Margin on L,N Items 10.00% (S\$)	219.40
Total Parts (S\$)	2,413.40

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rates on Miscellaneous Items

Particulars	Amount
<u>Miscellaneous Items</u>	
CAR PLATE NUMBER WITH HOLDER	Pin 50.00 X
REAR BUMPER CLIPS	Me 35.00 —
1 REAR END PANEL GARNISH CLIPS	Me 30.00 —
1 REAR FENDER INNER SHIELD CLIPS LH & RH	Na 80.00 X
1 REAR TAILGATE TRIM BOARD CLIPS	Me 35.00 ✓
1 REVERSE SENSOR SET	Shaf 2000 320.00
1 SEALANT	Me 400 80.00
Sub Total (S\$)	630.00

Estimates on Labour

Particulars	Lab.Type	Amount
<u>Labour Items</u>		
SPRAY PAINT ON ALL AFFECTED AREA	New	800 1,500.00
LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	700 1,500.00
3 TO CHECK WIRING SYSTEM & LIGHT	New	200 120.00
4 TO APPLY ANTI RUST TREATMENT	New	600 120.00
5 TO REMOVE/RELACE/REFIX TAIL GATE COMPARTMENT, MECHESISM TO NEW TAILGATE	New	600 150.00
6 TO REMOVE/REFIX/REPLACE REAR WINDSCREEN TO NEW TAILGATE	New	1200 150.00
7 TO REMOMVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	New	600 180.00
8 TO REMOVE/REFIX REVERSE CAMERA	New	400 100.00
9 TO REMOVE/REPLACE/REFIX REAR REVERSE SENSOR	New	500 100.00
Gross Labour Cost (S\$)		3,920.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >