4/3/23, 9:58 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000202/UVP3Q2

03/04/2023 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00248272200

**Claimant Vehicle** No:

SJK8558D

Insured

SJR5581T

Vehicle No:

Date of Loss:

30/12/2022

Nature of Claim: TP

Claim No:

SNM23D200061/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SJK8558D Reg No:

Make & Model: HONDA FREED HYBRID, 1.5 (A) Engine No: LEB5595029 Reg. Date: 28/08/2018 (Man. Year: 2018) Chassis No: GB71062910 Colour: Black Odometer: 148533 km

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

**Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15 Rear Left Side: Front Left Side: Falken 6 mm Falken 6 mm Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 3,029.76   | 803.28     | 2,226.48   | 73.49  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 1,325.00   | 760.00     | 565.00     | 42.64  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 4,354.76   | 1,563.28   | 2,791.48   | 64.10  |
| Approved Total (Overridden) (S\$) |            | 1,250.00   |            |        |
| (S\$)                             | 4,354.76   | 1,250.00   | 3,104.76   | 71.30  |
| + GST 8.00/8.00% (S\$)            | 348.38     | 100.00     | 248.38     | 71.30  |
| Nett Amount (S\$)                 | 4,703.14   | 1,350.00   | 3,353.14   | 71.30  |

**INSPECTION** 

Date of Assignment: 18/02/2023

Progressive Car Care Pte Ltd (HQ) Date Inspected: 15/02/2023 Inspected At: Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/3/23, 9:58 AM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2023)

Parts: M1-MPV HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK8558D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| No.   | Qty    | Part No.        | Particulars                       | Condition                 | Repairer's  | Amount     |
|-------|--------|-----------------|-----------------------------------|---------------------------|-------------|------------|
| 1     | 1      |                 | *FRONT BUMPER                     | Deep Cut                  | 897.20 FL   | *897.20 FL |
| 2     | 2      |                 | *FRONT BUMPER SIDE HOLDER -LH/RH  | Not Necessary             | 48.60 FL    | *- FL      |
| 3     | 10     |                 | *FRONT BUMPER CLIPS               | Necessary                 | 38.00 FL    | *38.00 FL  |
| 4     | 1      |                 | *HEAD LAMP -RH                    | Not Necessary             | 1,453.20 FL | *- FL      |
| 5     | 1      |                 | *HEAD LAMP LOWER BRACKET -RH      | Not Necessary             | 36.50 FL    | *- FL      |
| 6     | 1      |                 | *FRONT FENDER -RH                 | Repair                    | 540.20 FL   | *- FL      |
| 7     | 10     |                 | *FRONT FENDER COWLING CLIPS -RH   | Not Necessary             | 38.00 FL    | *- FL      |
| 8     | 1      |                 | *FRONT FENDER COWLING -RH         | Not Necessary             | 120.80 FL   | *- FL      |
| 9     | 1      |                 | *FRONT FENDER HYBRID WORDINGS -RH | Necessary                 | 68.90 FL    | *68.90 FL  |
| 10    | 1      |                 | *FRONT RIM -RH                    | Repair                    | 363.40 FL   | *- FL      |
| 11    | 1      |                 | *FRONT WHEEL COVER                | Not Necessary             | 182.40 FL   | *- FL      |
| F=Fra | nchise | part. L=ListIte | emDisc.                           | _                         |             |            |
|       |        |                 |                                   | Sub Total (S\$)           | 3,787.20    | 1,004.10   |
|       |        |                 | - List Item Discount on I         | Litems 20.00/20.00% (S\$) | 757.44      | 200.82     |
|       |        |                 |                                   | Total Parts (S\$)         | 3,029.76    | 803.28     |
|       |        |                 | Report was unsubmitted during     | g this print-out.         |             |            |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No         | Particulars                                     | Lab.Type               | Repairer's | Amount |
|------------|---|------------------------|------------|--------|
| <u>Lab</u> | our Items                                       |                        |            |        |
| 1          | TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PA | ARTS New               | 500.00     | 200.00 |
| 2          | TO RESPRAY PAINT ON ACCIDENT PORTIONS           | New                    | 600.00     | 480.00 |
| 3          | TO CHECK WIRING                                 | New                    | 40.00      | 20.00  |
| 4          | TO REMOVE, REPLACE RIM & TYRE BALANCING         | New                    | 45.00      | 0.00   |
| 5          | TO TUFF -KOTE                                   | New                    | 60.00      | 0.00   |
| 6          | TO 4 WHEEL ALIGNMENT                            | New                    | 80.00      | 60.00  |
|            | Gr  | oss Labour Cost (S\$)  | 1,325.00   | 760.00 |
|            | Report was unsubmitted                          | during this print-out. |            |        |

< END OF ESTIMATES >