2/3/23, 1:43 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000216/UWP3Q2

03/02/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00155432100

TP

Claimant Vehicle

SME4443Z

Insured

No:

Vehicle No:

GBA7579Y

Date of Loss:

03/01/2023

Nature of Claim:

Claim No:

SNM23D200084/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

SME4443Z Reg No:

VOLKSWAGEN GOLF, 1.4 SV TSI HL (A) Make & Model:

18/04/2019 (Man. Year: 2018)

Engine No: Chassis No: CZC998179

Colour:

Red

Odometer:

WVWZZZAUZKW661138 54825 km

Engine Capacity: Market Value/New Car 1395 cc

Price:

Reg. Date:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable): **CONDITION OF TYRES**

Yes **Engine Modification:** No Pre-accident Condition:

225/45 R17

Front Tyre Size: Front Left Side:

225/45 R17 Continental 6 mm

Rear Left Side: Rear Right Side:

Rear Tyre Size:

Continental 6 mm Continental 6 mm

Front Right Side: Continental 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,958.71	5,517.41	2,441.30	30.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	1,240.00	650.00	34.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,848.71	6,757.41	3,091.30	31.39
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	9,848.71	5,400.00	4,448.71	45.17

INSPECTION

Date of Assignment: 02/02/2023

Quan De Motor Trading

BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY Date Inspected: 09/01/2023 Inspected At:

SINGAPORE 417883

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager:

XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/3/23, 1:43 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2023)

Parts: 144 VOLKSWAGEN GOLF 1.4 SV TSI HL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SME4443Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	1,076.45 FL	*1,076.45 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Bent	68.85 FL	*68.85 FL
3	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	366.00 FL	*-FL
4	1		*HEADLAMP RH	Broken	2,087.95 FL	*2,087.95 FL
5	1		*FRONT FENDER RH	Dented	642.23 FL	*642.23 FL
6	1		*FRONT DOOR RH	Dented / Bent	1,215.42 FL	*1,215.42 FL
7	1		*FRONT DOOR INNER RUBBER RH	Necessary	189.00 FL	*189.00 FL
8	1		*FRONT DOOR MIRROR ASSY RH	Damaged	680.00 FL	*680.00 FL
9	1		*FRONT DOOR MIRROR COVER RH	Damaged	115.00 FL	*115.00 FL
10	1		*BONNET	Repair	1,591.00 FL	*- FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*FRONT SPORT RIM RH	Repair	680.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	8,761.90	6,124.90
			- List Item Discount on	803.19	607.49	
				Total Parts (S\$)	7,958.71	5,517.41
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REFIX FRONT PDC SENSOR	New	80.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	80.00	60.00
4	TO SPRAY RUST PROOFING	New	80.00	60.00
5	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS	New	700.00	400.00
6	SPRAY PAINTING	New	900.00	700.00
	Gross L	abour Cost (S\$)	1,890.00	1,240.00
	Report was unsubmitted durin	a this print-out		

< END OF ESTIMATES >