

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000217/UQP3Q2**Date:** 19/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00187482202		
Claimant Vehicle No :	SLD7216K	Insured Vehicle No :	SMT2127X		
Date of Loss:	04/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200118/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD7216K	Engine No:	LEB5079511
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31129494
Reg. Date:	27/06/2016 (Man. Year: 2016)	Odometer:	125904 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,381.84	2,984.40	4,397.44	59.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,580.00	1,340.00	45.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,301.84	4,564.40	5,737.44	55.69
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	10,301.84	3,650.00	6,651.84	64.57
+ GST 8.00/8.00% (S\$)	824.15	292.00	532.15	64.57
Nett Amount (S\$)	11,125.99	3,942.00	7,183.99	64.57

INSPECTION

Date of Assignment:	17/01/2023	BLK 9006 TAMPINES ST 93 #01-200
Date Inspected:	09/01/2023 Inspected At:	SINGAPORE 528840
Estimated Period of Repair:	4.0 days	Repairer:Falcon-Air Auto Services Pte Ltd (Sin Ming)

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD7216K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	853.00 FL	*752.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	70.00 FL	*- FL
3	1		*REAR BUMPER UNDERCOVER	Deformed / Torn	318.00 FL	*318.00 FL
4	1		*ANTENNA ASSY -SMARYKEY	Not Necessary	134.00 FL	*- FL
5	1		*BUZZER	Not Necessary	93.00 FL	*- FL
6	1		*TAILGATE	Badly Dented	1,197.00 FL	*953.00 FL
7	1		*SET TAILGATE GLASS MOULDING	Necessary	188.00 FL	*118.00 FL
8	1		*TAILGATE LOGO	Not Necessary	87.00 FL	*- FL
9	1		*TAILGATE VEZEL EMBLEM	Necessary	89.00 FL	*56.00 FL
10	1		*TAILGATE LOCK	Twisted	283.00 FL	*145.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	165.00 FL	*108.00 FL
12	1		*TAILGATE TRIM BOARD	Deformed / Cracked	353.00 FL	*266.00 FL
13	1		*REAR END PANEL	Repair	562.00 FL	*- FL
14	1		*REAR END PANEL GARNISH	Not Necessary	296.00 FL	*- FL
15	1		*REAR FENDER INNER TRIM	Not Necessary	760.00 FL	*- FL
16	2		*REAR FENDER ARCH GARNISH	Torn	392.00 FL	*392.00 FL
17	2		*TAILLAMP	Not Necessary	1,173.40 FL	*- FL
18	2		*TAILGATE LAMP	Not Necessary	731.40 FL	*- FL
19	1		*TAILGATE HYBRID EMBLEM	Necessary	95.00 FL	*85.00 FL
20	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
21	1		*SET REAR BUMPER UNDERCOVER CLIPS	Necessary	50.00 FS	*50.00 FS
22	1		*TAILGATE BODY SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*TAILGATE GLASS INNER SEAL	Necessary	50.00 FS	*40.00 FS
25	1		*SET TAILGATE TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
27	1		*SET REAR FENDER INNER TRIMS CLIPS	Not Necessary	80.00 FS	*- FS
28	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
29	1		*SET REAR FENDER ARCH GARNISH CLIP	Not Necessary	50.00 FS	*- FS
30	1		*SET REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,949.80	3,623.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,567.96	638.60
Total Parts (\$\$)	7,381.84	2,984.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	TRANSFER TAILGATE GLASS	New	120.00	120.00
3	TRANSFER TAILGATE PARTS	New	120.00	60.00
4	INSTALL REVERSE SENSOR }	New	150.00	50.00
5	INSTALL REVERSE CAMERA }	New	0.00	0.00
6	ANTI RUST }	New	150.00	0.00
7	TO APPLY BODY SEALANT ON BODY PARTS	New	150.00	0.00
8	TO RNR INNER TRIMS AND GARNISHES	New	180.00	80.00
9	LABOUR /PANEL BEATING	New	1,000.00	550.00
10	SPRAY PAINTING	New	1,000.00	700.00
Gross Labour Cost (S\$)			2,920.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >