

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23000218/RVP3Q2**Date:** 01/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00129612200		
Claimant Vehicle No :	GBH918L	Insured Vehicle No :	SMC8901C		
Date of Loss:	03/12/2022	Nature of Claim:	TP	Claim No:	SNM23D200143/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH918L</b>	Engine No:	1KD2752369
Make & Model:	TOYOTA HIACE, 3.0 D TURBO (M)	Chassis No:	JTFHT02PX00233962
Reg. Date:	10/01/2018 (Man. Year: 2017)	Odometer:	284504 km
Colour:	Orange		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,735.00	1,535.00	200.00	11.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,010.00	390.00	27.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,135.00</b>	<b>2,545.00</b>	<b>590.00</b>	<b>18.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	3,135.00	2,000.00	1,135.00	36.20
<b>+ GST 7.00/7.00% (S\$)</b>	219.45	140.00	79.45	36.20
<b>Nett Amount (S\$)</b>	<b>3,354.45</b>	<b>2,140.00</b>	<b>1,214.45</b>	<b>36.20</b>

**INSPECTION**

Date of Assignment:	06/01/2023		
Date Inspected:	06/01/2023	Inspected At:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Feb 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH918L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR LH	Buckled	980.00 FL	*980.00 FL
2	1		*ROCKER PANEL LH (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*ADVERTISEMENT STICKER PANELS LH	Necessary	1,000.00 FS	*800.00 FS
					Sub Total (S\$)	1,980.00 1,780.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	245.00 245.00
					Total Parts (S\$)	1,735.00 1,535.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	600.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	500.00
3	TO REMOVE AND TRANSFER DOOR COMPONENTS	New	150.00	60.00
4	RUST PROOFING	New	50.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>1,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >