



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDU 57D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	2,399.00	-
1	BOOTLID LOGO	NECESSARY	145.00	95.00
1	BOOTLID EMBLEM E250	NECESSARY	94.21	94.21
1	BOOTLID INNER LOCK	NOT NECESSARY	583.60	-
1	BOOTLID WEATHER STRIP	NOT NECESSARY	495.60	-
1	REAR BUMPER	DEFORMED	2,244.00	1,874.00
1	REAR BUMPER DIFFUSER	CRACKED	683.36	485.00
1	REAR BUMPER DIFFUSER OUTER CHROME	DENTED	278.00	278.00
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	375.72	-
2	REAR BUMPER REFLECTOR	NOT NECESSARY	337.20	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	751.33	-
1	REAR BUMPER BRACKET	NOT NECESSARY	101.82	-
6	REAR BUMPER REVERSE SENSOR	MALFUNCTION (2PCS ONLY)	1,470.00	458.00
1	REAR BUMPER INNER CARRIAGE	DEFORMED	582.31	278.00
1	KICK SENSOR GARNISH	NOT NECESSARY	417.65	-
2	REAR BUMPER INNER SIDE RETAINER	NOT NECESSARY	384.00	-
1	REAR END PANEL	NOT NECESSARY	1,752.30	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	347.74	-
1	REAR EXHAUST PIPE TIP	NOT NECESSARY	917.40	-
2	TAILLAMP	NOT NECESSARY	2,188.00	-
2	TAILLAMP LOWER BRACKET	O/S CRACKED	370.00	185.00
	LESS 10% DISCOUNT		-1,691.82	-374.73
			15,226.42	3,372.48
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	BOOTLID SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET BOOTLID OUTER GARNISH MOULDING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	CRACKED	60.00	30.00

Report Ref No. CS3/GRB22010737/Dqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER DIFFUSER CLIPS (SN)	NOT NECESSARY	60.00	-
6	REAR BUMPER REVERSE SENSOR SEAL (SN)	NECESSARY	288.00	60.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
2	TAILLAMP SEAL (SN)	NOT NECESSARY	120.00	-
2	SET TAILLAMP CLIPS (SN)	NOT NECESSARY	120.00	-
2	SET WRAP STICKER (SN)	NOT NECESSARY	1,600.00	-
			2,708.00	90.00
	LABOUR			
	R&R BOOTLID COMPONENT.	NOT NECESSARY	150.00	-
	R&R REAR BUMPER REVERSE SENSOR.		100.00	30.00
	DIAGNOSTIC & RESET FAULT CODE.		300.00	150.00
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	CHECK WIRING.		100.00	40.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	180.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		1,600.00	300.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,600.00	300.00
			4,530.00	820.00
GRAND TOTAL			22,464.42	4,282.48
RECOMMENDED COST OF REPAIRS				4,282.48

Report Ref No. CS3/GRB22010737/Dqy3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.