



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 178R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FASCIA-RR BPR (DISC 10%)	DEFORMED	758.48	682.63
1	FASCIA-RR BPR LWR (DISC 10%)	DEFORMED	230.68	207.61
1	LAMP ASM-RR FOG - RH (DISC 10%)	CRACKED	189.07	170.16
1	BAR ASM-RR BPR IMP (DISC 10%)	BENT	339.76	305.78
1	FINISHER-RR BPR - RH	NOT NECESSARY	47.42	-
1	FINISHER-RR BPR - LH	NOT NECESSARY	47.42	-
1	BRACKET ASM-RR BPR FASCIA SI-RH	NOT NECESSARY	29.85	-
1	BRACKET ASM-RR BPR FASCIA SI-LH	NOT NECESSARY	29.84	-
1	BRACKET-RR BPR FASCIA SI MTG - LH	NOT NECESSARY	46.08	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - LH	NOT NECESSARY	13.20	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	NOT NECESSARY	12.90	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	NOT NECESSARY	12.90	-
1	BRACKET-RR BPR FASCIA LWR MTG - RH	NOT NECESSARY	12.80	-
1	BRACKET-RR BPR FASCIA LWR MTG - LH	NOT NECESSARY	12.80	-
1	BAR ASM-RR BPR IMP	NOT NECESSARY	339.76	-
1	LAMP ASM-RR FOG - RH	NOT NECESSARY	189.07	-
1	LAMP ASM-RR FOG - LH	NOT NECESSARY	36.30	-
3	SENSOR-RR PARK DIST CONT @\$65.00	NOT NECESSARY	195.00	-
1	PANEL ASM-RR END	TO REPAIR SEE LABOUR	708.66	-
			3,251.99	1,366.18
<u>LABOUR</u>				
PANEL BEATING AND BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL ASM-RR END.			1,200.00	500.00
SPRAY PAINT.			888.00	370.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		NOT NECESSARY	120.00	-
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	40.00

Report Ref No. NS/INC23000221/Gvy3m4



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	150.00
	ISOLATED OF (EV) (NET).		150.00	150.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,088.00	1,210.00
GRAND TOTAL			6,339.99	2,576.18
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,576.18

Report Ref No. NS/INC23000221/Gvy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.