

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG23000227/SNCE2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant:	TAY JOO KIAT (ZHENG YUJI)	Policy No:	1800142539-04	
Date of Loss:	27/12/2022	Nature of Claim:	OD	Claim No: 4504702203SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9601X		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)	Engine No:	CZE846164
Reg. Date:	29/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V0K1002911
Colour:	Blue	Odometer:	41668 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$107,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,080.00	6,397.60	13,682.40	68.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,562.00	3,902.00	4,660.00	54.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,642.00	10,299.60	18,342.40	64.04
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	28,042.00	9,699.60	18,342.40	65.41
+ GST 8.00/8.00% (S\$)	2,243.36	775.97	1,467.39	65.41
Nett Amount (S\$)	30,285.36	10,475.57	19,809.79	65.41

INSPECTION

Date of Assignment:	09/01/2023	
Date Inspected:	04/01/2023	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,432.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	571.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	636.00 FS	*- FS
7	2		*FRONT BUMPER TRIM COVER - LH / RH	Not Necessary	364.00 FS	*- FS
8	2		*FRONT WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,578.00 FS	*1,262.40 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
11	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
12	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	136.00 FS	*- FS
16	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
17	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	56.00 FS	*- FS
18	1		*FRONT BUMPER AIR GUIDE SEAL - RH OUTER	Not Necessary	9.00 FS	*- FS
19	1		*FRONT BUMPER AIR GUIDE - UPPER CENTRE	Not Necessary	14.00 FS	*- FS
20	1		*FRONT BUMPER CATCH HOOK	Not Necessary	71.00 FS	*- FS
21	1		*FRONT NO PLATE	Cracked	80.00 FS	*60.00 FS
22	1		*REAR BUMPER	Cut	2,317.00 FS	*1,853.60 FS
23	1		*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
24	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	36.00 FS	*- FS
25	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	67.00 FS	*- FS
26	1		*REAR BUMPER SPOILER	Not Necessary	264.00 FS	*- FS
27	2		*REAR WHEEL HOUSING ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
28	2		*REAR BUMPER REFLECTOR - LH / RH	Not Necessary	92.00 FS	*- FS
29	2		*REAR INNER TAIL LIGHT - LH / RH	Not Necessary	1,948.00 FS	*- FS
30	2		*REAR INNER TAIL LIGHT TRIM - LH / RH	Not Necessary	68.00 FS	*- FS
31	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	642.00 FS	*- FS
32	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	63.00 FS	*- FS
33	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
34	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
35	1		*SET REAR BUMPER WIRING	Not Necessary	572.00 FS	*- FS
36	1		*REAR LID	Dented	3,657.00 FS	*2,925.60 FS
37	1		*REAR LID FLAP GASKET	Not Necessary	229.00 FS	*- FS
38	1		*REAR LID LOCK	Not Necessary	211.00 FS	*- FS
39	1		*REAR LID LOCK COVER	Not Necessary	8.00 FS	*- FS
40	1		*REAR LID LOCK STRIKER	Not Necessary	56.00 FS	*- FS
41	1		*PACKING ADHESIVE	Necessary	21.00 FS	*16.80 FS
42	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
43	1		*A3 INSCRIPTION	Necessary	104.00 FS	*82.80 FS
44	2		*LIFT CYLINDER - LH / RH	Not Necessary	312.00 FS	*- FS
45	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
46	1		*REAR NO PLATE	Dented	60.00 FS	*60.00 FS
47	1		*SUNDRIES	Necessary	500.00 FS	*2.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **20,080.00** **6,397.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
5	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
6	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING	New	3,000.00	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,500.00	1,000.00
Gross Labour Cost (\$\$)			8,562.00	3,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >