

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG23000243/UYA3Q2  
**Date:** 17/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220017338
<b>Claimant Vehicle No :</b>	SGH2448D	<b>Insured Vehicle No :</b>	SGC7777Y
Date of Loss:	06/01/2023	Nature of Claim:	TP
		Claim No:	9267101651SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGH2448D</b>	Engine No:	2ARU268041
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004009928
Reg. Date:	19/11/2015 (Man. Year: 2015)	Odometer:	190640 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Sumitomo 6 mm	Rear Left Side:	Sumitomo 6 mm
Front Right Side:	Sumitomo 6 mm	Rear Right Side:	Sumitomo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,502.28	7,024.50	8,477.78	54.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	2,230.00	2,740.00	55.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,472.28</b>	<b>9,254.50</b>	<b>11,217.78</b>	<b>54.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,472.28</b>	<b>7,400.00</b>	<b>13,072.28</b>	<b>63.85</b>
<b>+ Car Rental (8.0 x S\$130.00/day) (S\$)</b>		1,040.00		
<b>+ Doc/Search Fee (S\$)</b>		26.75		
<b>+ Other Costs (S\$)</b>		50.00		
<b>Nett Liability (S\$)</b>		<b>8,516.75</b>		

**INSPECTION**

Date of Assignment:	09/01/2023		
Date Inspected:	09/01/2023	Inspected At:	SPEEDWERKZ PTE LTD 1 Kaki Bukit Ave 6 #01-73 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented / Buckled	1,335.20 FL	*1,335.20 FL
2	1		*REAR BOOT LOCK	Twisted	238.70 FL	*238.70 FL
3	1		*REAR BOOT LOCK CATCH	Not Necessary	45.60 FL	*- FL
4	1		*REAR BOOT EMBLEM (CAMRY)	Necessary	97.60 FL	*97.60 FL
5	1		*REAR BOOT EMBLEM (2.5)	Necessary	56.70 FL	*56.70 FL
6	2		*REAR BOOT REFLECTOR	Cracked	945.60 FL	*945.60 FL
7	1		*REAR BOOT CENTER CHROME	Cracked	424.60 FL	*325.10 FL
8	1		*REAR BOOT RUBBER	Twisted	356.30 FL	*356.30 FL
9	2		*REAR BOOT HINGES	Not Necessary	227.60 FL	*- FL
10	1		*REAR BOOT INNER BOARD	Not Necessary	365.90 FL	*- FL
11	1		*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	289.30 FL	*- FL
12	2		*REAR BOOT NUMBER PLATE LAMP	Not Necessary	74.00 FL	*- FL
13	2		*REAR FENDER	Repair	3,360.00 FL	*- FL
14	2		*REAR FENDER INNER GARNISH	Deformed / Torn	1,029.80 FL	*1,029.80 FL
15	2		*REAR TAIL LAMP	Cracked	1,578.40 FL	*1,339.00 FL
16	2		*REAR TAIL LAMP PANEL	Bent	489.60 FL	*489.60 FL
17	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	95.80 FL	*- FL
18	1		*REAR END PANEL	Badly Dented	749.90 FL	*685.10 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	233.50 FL	*233.50 FL
20	1		*REAR BUMPER	Distorted	1,429.00 FL	*725.10 FL
21	1		*REAR BUMPER SIDE RETAINER	Bent	111.20 FL	*111.20 FL
22	2		*REAR BUMPER REFLECTORS	Cracked	136.00 FL	*136.00 FL
23	2		*REAR BUMPER PARKING SENSOR	Shorted	470.00 FL	*470.00 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	596.50 FL	*415.20 FL
25	1		*REAR SPARE TYRE PANEL	Repair	1,352.00 FL	*- FL
26	1		*RAER SPARE TYRE TOOL TRAY SPONGE	Torn	256.30 FL	*256.30 FL
27	1		*REAR EXHAUST SILENCER	Not Necessary	1,856.00 FL	*- FL
28	2		*REAR EXHAUST RUBBER	Not Necessary	147.80 FL	*- FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	135.20 FL	*- FL
30	1		*REAR NUMBER PLATE	Bent	45.00 FS	*40.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
32	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
33	1		*SET REAR REVERSING SENSOR	Repeated	450.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>19,199.10</b>	<b>9,336.00</b>
<b>- List Item Discount on L Items 20.00/25.00% (\$)</b>	3,696.82	2,311.50
<b>Total Parts (\$)</b>	<b>15,502.28</b>	<b>7,024.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	150.00	20.00
2	APPLY ANTI RUST	New	200.00	80.00
3	REMOVE & REFIX CUSHION UPHOLSTERY	New	350.00	80.00
4	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
5	REMOVE AND REFIX REVERSE SENSOR	New	160.00	50.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	160.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACE PARTS	New	2,000.00	900.00
8	TO SPRAY PAINTING	New	1,800.00	1,100.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,970.00</b>
				<b>2,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >