

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG23000244/UYA3Q2
Date: 17/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210110048
Claimant Vehicle No :	SMW2562G	Insured Vehicle No :	SNB9416Z
Date of Loss:	05/01/2023	Nature of Claim:	TP
		Claim No:	3649671999SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW2562G		
Make & Model:	SSANGYONG TIVOLI, 1.5 G DLX 6AT 2WD ESP E6 FL (A)	Engine No:	17595002010776
Reg. Date:	11/11/2020 (Man. Year: 2020)	Chassis No:	KPT30B1YSLP315925
Colour:	Silver	Odometer:	42964 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,957.26	5,469.75	8,487.51	60.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	2,480.00	1,800.00	42.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,237.26	7,949.75	10,287.51	56.41
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	18,237.26	6,300.00	11,937.26	65.46
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		26.75		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		6,766.75		

INSPECTION

Date of Assignment:	09/01/2023	
Date Inspected:	09/01/2023	Inspected At: SPEEDWERKZ PTE LTD (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 147807
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	80.30 FL	*- FL
2	1		*REAR BOOT COVER	Repair	1,860.00 FL	*- FL
3	1		*REAR BOOT COVER LOGO	Not Necessary	110.00 FL	*- FL
4	1		*REAR BOOT COVER EMBLEM (TIVOLI)	Necessary	62.00 FL	*62.00 FL
5	1		*REAR BOOT EMBLEM	Necessary	64.00 FL	*64.00 FL
6	1		*REAR BOOT INNER LOCK	Not Necessary	233.70 FL	*- FL
7	2		*REAR BOOT NUMBER PLATE LIGHT	Not Necessary	94.00 FL	*- FL
8	1		*REAR BOOT COVER INNER BOARD	Not Necessary	385.10 FL	*- FL
9	2		*REAR BOOT COVER ABSORBER HOLDER	Not Necessary	320.00 FL	*- FL
10	1		*REAR BUMPER	Distorted	1,650.29 FL	*912.75 FL
11	1		*REAR BUMPER LOWER	Distorted	865.00 FL	*865.00 FL
12	2		*REAR BUMPER REFLECTOR	Not Necessary	136.00 FL	*- FL
13	1		*REAR BUMPER CENTRE LAMP	Not Necessary	167.50 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Cracked	378.70 FL	*378.70 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	104.00 FL	*- FL
16	1		*REAR BUMPER SIDE ARCH GARNISH	O/S Distorted	262.00 FL	*131.00 FL
17	1		*REAR TAIL LAMP RH	Cracked	885.00 FL	*885.00 FL
18	1		*REAR EXHAUST SILENCER BOX	Not Necessary	867.20 FL	*- FL
19	1		*REAR ADBLUE FLUID TANK	Not Necessary	1,860.00 FL	*- FL
20	1		*REAR END PANEL	Badly Dented	851.70 FL	*851.70 FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	141.70 FL	*- FL
22	1		*REAR LUGGAGE PANEL	Not Necessary	922.30 FL	*- FL
23	1		*REAR LUGGAGE PENAL TOP COVER	Not Necessary	227.60 FL	*- FL
24	1		*REAR FENDER RH	Buckled	1,685.00 FL	*1,545.00 FL
25	1		*REAR FENDER UNDER TRIM	O/S Torn	653.60 FL	*326.80 FL
26	1		*REAR TOOL TRAY	Not Necessary	213.60 FL	*- FL
27	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
28	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR END PENAL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
30	1		*SET REAR ARCH GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
31	1		*ADBLUE CHEMICAL	Not Necessary	80.00 FS	*- FS
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,465.29	6,071.95
- List Item Discount on L Items 10.00/10.00% (S\$)	1,508.03	602.20
Total Parts (S\$)	13,957.26	5,469.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	250.00	20.00
2	APPLY ANTI RUST CHEMICAL	New	250.00	80.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	160.00	0.00
4	TO REMOVE AND REPLACE REAR TRIMMING, CUSHION SEAT ETC	New	250.00	80.00
5	TO REMOVE AND REPLACE ADBLUE TANK	New	120.00	0.00
6	TO SPRAY PAINTING AND ETC	New	1,500.00	1,100.00
7	TO REMOVE AND REPLACE EXHAUST PIPE	New	150.00	0.00
8	TO REMOVE AND REPLACE SPARE PARTS AND PENAL BEATING	New	1,600.00	1,200.00
			Gross Labour Cost (S\$)	4,280.00
				2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >