

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000246/UPA3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900002620
Claimant Vehicle No :	SMZ2134T	Insured Vehicle No :	SMH1119P
Date of Loss:	07/01/2023	Nature of Claim:	TP
		Claim No:	5886200768SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ2134T		
Make & Model:	HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A)	Engine No:	G4FMMU001879
Reg. Date:	16/04/2021 (Man. Year: 2021)	Chassis No:	KMHLN41ETNU172610
Colour:	Grey	Odometer:	103979 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,946.72	3,810.56	3,136.16	45.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,390.00	1,660.00	54.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,996.72	5,200.56	4,796.16	47.98
+ GST 8.00/8.00% (S\$)	799.74	416.04	383.70	47.98
Nett Amount (S\$)	10,796.46	5,616.60	5,179.86	47.98
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,818.60		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment:	09/01/2023	
Date Inspected:	09/01/2023	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	2,782.00 FL	*2,023.20 FL
2	1		*BOOTLID REAR LOGO	Not Necessary	75.80 FL	*- FL
3	1		*BOOTLID AVANTE EMBLEM	Necessary	42.00 FL	*42.00 FL
4	1		*BOOTLID S EMBLEM	Serviceable	35.00 FL	*- FL
5	1		*BOOTLID REFLECTOR CENTRE	Cracked	962.20 FL	*962.20 FL
6	1		*BOOTLID INNER LOCK	Damaged	148.00 FL	*148.00 FL
7	1		*BOOTLID WEATHERSTRIP	Not Necessary	166.00 FL	*- FL
8	1		*REAR BUMPER	Dented / Deformed	481.00 FL	*470.80 FL
9	1		*REAR BUMPER CENTRE GARNISH	Grazed	354.00 FL	*340.60 FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 FL	*- FL
11	1		*REAR BUMPER SPONGE	Not fitted	245.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	329.00 FL	*294.80 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	302.00 FL	*- FL
14	3		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Twisted	75.00 FL	*75.00 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
16	1		*REAR END PANEL	Repair	537.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	188.90 FL	*106.60 FL
18	2		*TAILLAMPS	Not Necessary	1,318.00 FL	*- FL
19	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
21	2		*REAR BUMPER REINFORCEMENT TOP BRACKETS	Not Necessary	50.00 FL	*- FL
					Sub Total (\$\$)	8,600.90 4,713.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,654.18 902.64
					Total Parts (\$\$)	6,946.72 3,810.56

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	100.00	30.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	550.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (S\$)			3,050.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >