6/19/23, 9:36 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI23000250/RNY3E2

19/06/2023 Date:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No:

YP6192J Insured Vehicle No: YN1128P

19/12/2022 Nature of Claim: TP Claim No: CDMCG22002742 Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP6192J

Make & Model: ISUZU FRR90SUQA-C, 5.2 D (M) Engine No: 4HK1575312

Reg. Date: 26/04/2017 (Man. Year: 2016) Chassis No: JALFRR907H7000027

Colour: Odometer: 252747 km White

Engine Capacity: 5193 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/90 R17.5 Rear Tyre Size: 225/90 R17.5 (D) Front Left Side: OHTSU 7 mm Rear Left Side: OHTSU 7/7 mm Front Right Side: Rear Right Side: OHTSU 7 mm OHTSU 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,580.00	2,580.00	1,000.00	27.93
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,400.00	1,900.00	500.00	20.83
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,980.00	4,480.00	1,500.00	25.08
	Approved Total (Overridden) (S\$)		3,550.00		
	(S\$)	5,980.00	3,550.00	2,430.00	40.64
	+ GST 8.00/8.00% (S\$)	478.40	284.00	194.40	40.64
	Nett Amount (S\$)	6,458.40	3,834.00	2,624.40	40.64

INSPECTION

Date of Assignment: 09/01/2023

Goldbell Engineering Pte Ltd (Tuas)

Date Inspected: 15/05/2023 Inspected At: No. 10 Tuas Avenue 18

Singapore 638894

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jun 2023)

Parts: N/A ISUZU FRR90SUQA-C 5.2 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP6192J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALUMINIUM PLATE 4X10 (3PCS)	Bent	1,650.00 FS	*1,450.00 FS
2	1		*SQUARE TUBE METAL 3X1 1/2	Bent	270.00 FS	*170.00 FS
3	1		*PLYWOOD	Cracked	260.00 FS	*160.00 FS
4	1		*METAL PLATE	Repair	380.00 FS	*-FS
5	1		*ANGLE BAR	Bent	150.00 FS	*100.00 FS
6	1		*SPRING LOCK	Not Working	160.00 FS	*120.00 FS
7	1		*RUBBER	Necessary	90.00 FS	*60.00 FS
8	4		*SILICONE	Necessary	160.00 FS	*160.00 FS
9	1		*RIVET (100PCS)	Necessary	60.00 FS	*60.00 FS
10	1		*COMPANY LOGO	Necessary	400.00 FS	*300.00 FS
F=Fra	nchise	part. S=SpcNe	tt.	-		
				Total Parts (S\$)	3,580.00	2,580.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	TO REMOVE AND REFIX AMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	1,500.00	1,200.00	
2	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC	New	900.00	700.00	
	Gross Labour Cost (S\$)		2,400.00	1,900.00	
Report was unsubmitted during this print-out.					

< END OF ESTIMATES >