

ASS. REC BY: Tauja

REF:

ALG.

CC3/AIG23000252/Tnp3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: fler 0

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$168K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLB 6322D Yr Regn: 2022 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: And A3 Sedan 1.5 C.C. 1498

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 924 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: W1442226Y4A1A049566

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 6/1/23

Premium Ubi

Frt N/S.

Date / Time Action / Instruction

Confirm final fig \$2,408.40 before excess \$0 & GST and 4 repair days.  
(red, \$13162.6, 85%)

Date/Time, File Pass to?

1) 04/05/23

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B.R. / ?

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. SI

Photos

Others



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0008/2023/EQ  
DATE : 6-Jan-23  
WIP : 57780

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/1/2023

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

OWNER'S NAME : MS LEOW KWEE HAR  
ADDRESS : 1 ELIAS GREEN  
#12-03  
SINGAPORE 519959  
TELEPHONE : HP +65 98288117  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7220144895  
VEHICLE NO : **SLB 6322 D**  
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI  
MODEL YEAR : 15/12/2022  
ENGINE NO : DFY 321661  
CHASSIS NO : WAUZZZGY4NA049066  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 4-Jan-23  
PLACE OF ACCIDENT : 8@TRADEHUB 21 CARPARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 6322 D**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	500
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 5,122.00</b>	


**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 6322 D**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,677.00	Ry
2	FRONT BUMPER FIXING PARTS	1	\$ 290.00	X
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 130.00	✓
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 433.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 265.00	X
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 67.00	X
7	FRONT BUMPER TRIM COVER - LH	1	\$ 104.00	X
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 171.00	int ✓
9	FRONT PARKING AID SENSOR BRACKET - LH	1	\$ 43.00	X
10	FRONT BUMPER GUIDE SECTION - LH	1	\$ 54.00	X
11	FRONT BUMPER COVER	1	\$ 93.00	X
12	CAUTION SIGN STICKER	1	\$ 16.00	✓
13	AIR CONDITIONER STICKER	1	\$ 9.00	✓
14	FRONT PARKING AID SENSOR - OUTER	1	\$ 279.00	X
15	FRONT PARKING AID SENSOR - LH	1	\$ 266.00	X
16	FRONT PARKING AID SEAL RING	4	\$ 52.00	X
17	FRONT FENDER - LH	1	\$ 1,241.00	Ry
18	FRONT FENDER RIVET	3	\$ 12.00	✓
19	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 32.00	✓
20	FRONT FENDER BRACKET - LH	1	\$ 46.00	X
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 5,280.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.


**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 6322 D**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - LH	1	\$ 35.00	✓
22	FRONT FENDER BRACE - LH	1	\$ 98.00	✓
23	FRONT WHEEL HOUSING LINER - LH	1	\$ 183.00	✓
24	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 22.00	✓
25	HEADLIGHT - LH	1	\$ 4,084.00	✓
26	HEADLIGHT HOSE - LH	1	\$ 28.00	✓
27	LIFT CYLINDER - LH	1	\$ 211.00	✓
28	LIFT CYLINDER HOSE	1	\$ 108.00	✓
29	SUNDRIES		\$ 400.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 10,449.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 5,122.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 15,571.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Tanpin 97495749  
Not Authorise Ex: H69  
6/1/23 @ 220 pm  
Resurvey before paint  
4 days  
Tanpin @ 11:00 am

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT