6/19/23, 10:55 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000256/RVP3Q2

19/06/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00201652100

Claimant Vehicle

FBR1558H

Insured

SLG1610D

No:

Vehicle No:

Date of Loss:

03/01/2023

Nature of Claim: TP

Claim No:

SNM23D200120/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBR1558H Reg No:

Make & Model: YAMAHA T150, 150cc

Engine No:

G3P3E0001241

Reg. Date: Colour:

04/03/2020 (Man. Year: 2019)

Chassis No: Odometer:

MH3UG131000001256 71281 km

Engine Capacity:

Market Value/New Car

150 cc N/A

Black

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Engine Modification: Yes

No Pre-accident Condition:

CONDITION OF TYRES Front Tyre Size:

60/80-17

Rear Tyre Size:

70/80-17

Front Left Side:

Maxxis 3 mm

Rear Left Side:

Maxxis 3 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,548.00	1,703.00	2,845.00	62.55
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,330.00	650.00	680.00	51.13
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	5,878.00	2,353.00	3,525.00	59.97

INSPECTION

Date Inspected:

Date of Assignment:

06/01/2023

11/01/2023

Inspected At:

Hkl Lim Team Motorsport (HQ)

BLK 1008 #01-24 BUKIT MERAH LANE 3

Singapore 159722

Estimated Period of Repair:

5.0 days

Adjuster: MOHD RASUL Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,465.00 NETT)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jun 2023)

Parts: N/A YAMAHA T150 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBR1558H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No	o. Particulars	Condition	Repairer's	Amount
1	1	*LAMP STAY	*Check	80.00 F	*- F
2	1	*METER ASSY	Not Necessary	380.00 F	*- F
3	2	*FRONT FORK ASSY LH/RH (PROTAPER)	*Check	480.00 F	*- F
4	1	*FRONT FORK UNDER BRACKET	*Check	250.00 F	*- F
5	1	*STEERING CONE BEARING	*Check	90.00 F	*- F
6	1	*FRONT FENDER	Not Necessary	80.00 F	*- F
7	1	*FRONT WHEEL RIM	Not Necessary	180.00 F	*- F
8	1	*FRONT WHEEL SHALF	*Check	45.00 F	*- F
9	2	*FRONT WHEEL BEARING	Not Necessary	40.00 F	*- F
10	1	*FRONT WHEEL BEARING OIL SEAL	Not Necessary	20.00 F	*- F
11	1	*FRONT BRAKE DISC	Not Necessary	150.00 F	*- F
12	1	*HEAD COWLING	Scratched	150.00 F	*150.00 F
13	1	*PILOT LIGHT	*Check	320.00 F	*- F
14	1	*FRONT SIGNALS RH	Scratched	80.00 F	*80.00 F
15	1	*HANDLE BAR	*Check	120.00 F	*-F
16	1	*HANDLE BAR GRIP	Cut	35.00 F	*35.00 F
17	1	*HANDLE BAR BALANCER	Not Necessary	30.00 F	*-F
18	1	*HANDLE BAR FRONT COVER	Cracked	85.00 F	*85.00 F
19	1	*HANDLE BAR REAR COVER	*Check	80.00 F	*-F
20	1	*FRONT NO PLATE	Scratched	15.00 F	*15.00 F
21	1	*BRAKE LEVER RCB	Scratched	48.00 F	*48.00 F
22	1	*HEADLIGHT	Cracked	320.00 F	*320.00 F
23	1	*FRONT BRAKE MASTER PUMP RCB	Scratched	160.00 F	*160.00 F
24	1	*HEAD PANEL	Scratched	90.00 F	*90.00 F
25	1	*EXHAUST END CAP	Scratched	60.00 F	*60.00 F
26	1	*REAR FOOT REST RH	Scratched	55.00 F	*55.00 F
27	1	*BASKET	Bent	55.00 F	*55.00 F
28	1	*BRAKE PEDAL	Bent	95.00 F	*95.00 F
29	1	*FRONT FOOT REST RH	Scratched	60.00 F	*60.00 F
30	1	*FRONT FOOT REST BRACKET	Not Necessary	120.00 F	*-F
31	1	*EXHAUST	Repair	380.00 F	*-F
31 32	1	*EXHAUST MUFFLER COVER	Scratched	80.00 F	*80.00 F
33	1	*REAR SIGNAL RH	Cracked	75.00 F	*75.00 F
აა 34	1	*SIDE FAIRING RH	Scratched	120.00 F	*120.00 F
35	1	*TAILBOARD RH	Scratched	120.00 F	*120.00 F
	nchise part.	IAILDUARU KII	Scratched	120.00 F	120.00 F
. –1 16	anomoe part.		Total Parts (S\$)	4,548.00	1,703.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	LABOUR	New	680.00	300.00		
2	BODY FRAME ALIGNMENT	New	650.00	350.00		
		Gross Labour Cost (S\$)	1,330.00	650.00		
Report was unsubmitted during this print-out.						

< END OF ESTIMATES >