

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000260/RWP3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00106242202

Claimant Vehicle No : SMU7854S **Insured Vehicle No :** GZ8320D

Date of Loss: 03/01/2023 Nature of Claim: TP Claim No: SNM23D200098/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU7854S**

Make & Model: BMW 216I, 1.5 ACTIVE TOURER (A) Engine No: 37225984B38A15A

Reg. Date: 28/08/2020 (Man. Year: 2020) Chassis No: WBA2X920407F85470

Colour: Grey Odometer: 49516 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,111.55 | 1,917.40 | 194.15 | 9.19 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,980.00 | 3,583.00 | 1,397.00 | 28.05 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 7,091.55 | 5,500.40 | 1,591.15 | 22.44 |
| + GST 8.00/8.00% (S\$) | 567.32 | 440.03 | 127.29 | 22.44 |
| Nett Amount (S\$) | 7,658.87 | 5,940.43 | 1,718.44 | 22.44 |

INSPECTION

Date of Assignment: 09/01/2023

Date Inspected: 16/01/2023 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 30 May 2023) |
| Parts: | 143 | BMW 216I 1.5 ACTIVE TOURER (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMU7854S) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|---------------------------------------|---------------|-------------------|-------------------|
| 1 | 1 | | *REAR BUMPER CARRIER | Bent | 505.35 FS | *505.35 FS |
| 2 | 1 | | *SUPPORT | Not Necessary | 48.45 FS | *- FS |
| 3 | 1 | | *REAR BUMPER TRIM STRIP (BLACK) | Cut | 105.30 FS | *105.30 FS |
| 4 | 1 | | *REAR BUMPER PANEL PRIMED (LINES PDC) | Deformed | 1,088.30 FS | *1,088.30 FS |
| 5 | 1 | | *LETTERING 216 I | Necessary | 65.60 FS | *65.60 FS |
| 6 | 1 | | *PLAQUE 74MM | Necessary | 72.85 FS | *72.85 FS |
| 7 | 2 | | *PLAQUE 74MM | Not Necessary | 145.70 FS | *- FS |
| 8 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *80.00 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| | | | | | Total Parts (S\$) | 2,111.55 1,917.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER ,ATTACHMENTS AND MAKE GOOD OF REAR BUMPER | New | 2,550.00 | 1,275.00 |
| 2 | TO PAINTING REAR BUMPER AND TAILGATE | New | 2,076.00 | 1,972.00 |
| 3 | TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| 4 | TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| Gross Labour Cost (\$\$) | | | 4,980.00 | 3,583.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >