

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23000261/KQY3Q2**Date:** 27/02/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMP9535B **Insured Vehicle No :** SJP4003M

Date of Loss: 03/01/2023 Nature of Claim: TP Claim No: DMPC2300001H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP9535B**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZR813125

Reg. Date: 24/10/2019 (Man. Year: 2019) Chassis No: NHP1707183318

Colour: Metallic Black Odometer: 104702 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: West Lake 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: West Lake 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,070.16	3,297.52	4,772.64	59.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,880.00	1,740.00	48.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,690.16	5,177.52	6,512.64	55.71
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	11,690.16	4,100.00	7,590.16	64.93

INSPECTION

Date of Assignment: 05/01/2023

Date Inspected: 05/01/2023 Inspected At: TSR AUTOMOTIVE PTE LTD (HQ)
160 SIN MING DRIVE, #06-01 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP9535B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,485.00 FL	*1,310.00 FL
2	1		*TAILGATE CENTER LOGO	Serviceable	78.00 FL	*- FL
3	1		*TAILGATE HYBRID EMBLEM	Necessary	98.00 FL	*98.00 FL
4	1		*TAILGATE WEATHERSTRIP (50%)	Cut	242.25 FS	*144.45 FS
5	1		*TAILGATE LOCK	Repair	318.50 FL	*- FL
6	1		*TAILGATE LOCK SENSOR	Serviceable	323.45 FL	*- FL
7	1		*TAILGATE W/SCREEN MOULDING	Necessary	228.00 FL	*128.00 FL
8	1		*TAILGATE LAMP RH	Serviceable	485.00 FL	*- FL
9	1		*TAILGATE TRIM BOARD	Serviceable	598.00 FL	*- FL
10	1		*TAILLAMP RH	Serviceable	685.00 FL	*- FL
11	1		*TAILLAMP PANEL RH (NPA)	Repair	0.00 FL	*- FL
12	1		*TAILLAMP LOWER BRACKET RH	Serviceable	220.00 FL	*- FL
13	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
14	1		*REAR FENDER UNDERSHIELD RH	Serviceable	298.00 FL	*- FL
15	1		*REAR FENDER INNER SIDE TRIM BOARD RH	Cracked	580.00 FL	*580.00 FL
16	1		*REAR BUMPER	Buckled	620.00 FL	*620.00 FL
17	1		*REAR BUMPER TOP GARNISH	Dented	380.15 FL	*230.00 FL
18	1		*REAR BUMPER TOP SIDE GARNISH RH	Dented	285.45 FL	*159.10 FL
19	1		*REAR BUMPER REFLECTOR RH	Serviceable	198.00 FL	*- FL
20	1		*SET REAR BUMPER SENSOR & CABLE	Dented	510.00 FS	*200.00 FS
21	2		*REAR BUMPER RETAINERS	Serviceable	280.00 FL	*- FL
22	1		*END PANEL	Bent	620.00 FL	*531.00 FL
23	1		*END PANEL TOP GARNISH	Mtg Distorted	442.00 FL	*168.00 FL
24	1		*FLOOR PANEL	Repair	1,288.00 FL	*- FL
25	1		*REAR CHASSIS RH (NPA)	Repair	0.00 FL	*- FL
26	1		*REAR EXHAUST (NPA)	Repair	0.00 FL	*- FL
27	2		*T REAR W/SCREEN SEALANT	Necessary	140.00 FS	*40.00 FS
28	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,447.80	4,253.55
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,377.64	956.03
Total Parts (\$\$)	8,070.16	3,297.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO DO CUTTING WELDING ,REPAIR ,REPLACE ON REAR ACCIDENT AFFECTED AREA	New	1,200.00	700.00
2	TO DO ANTI RUST	New	120.00	60.00
3	CHECKING WIRING SYSTEM ,REPLACE SENSOR ,AND REVERSE CAM ETC	New	150.00	60.00
4	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA ,INNER AND OUTER	New	1,000.00	750.00
5	TO DO SEALANT ,SEAL GAP ,WATERPROOFING ON CUT WELD AREA	New	250.00	30.00
6	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	120.00	60.00
7	TO REMOVE REFIX GARNISH SIDE TRIMS UPHOLSTERY ETC	New	280.00	100.00
8	REMOVE REFIX REAR W/SCREEN	New	120.00	120.00
9	TO DO REAR CHASSIS REPAIR ,CHASSIS BODY ALIGNMENT	New	300.00	0.00
10	TO REPAIR REAR EXHAUST	New	80.00	0.00
Gross Labour Cost (\$\$)			3,620.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >