



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 7209A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	899.00	-
1	FRONT DOOR HINGE RH (UPPER) (CONSISTENT)	NOT NECESSARY	49.00	-
1	FRONT DOOR HINGE RH (LOWER) (CONSISTENT)	NOT NECESSARY	49.00	-
1	FRONT DOOR CHECK RH (CONSISTENT)	NOT NECESSARY	46.00	-
1	FRONT DOOR RH TRIM BOARD (CONSISTENT)	NOT NECESSARY	453.00	-
1	FRONT DOOR RH WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	139.00	-
1	REAR DOOR RH (CONSISTENT)	DENTED/BENT	1,009.00	811.00
1	REAR DOOR HINGE RH (UPPER) (CONSISTENT)	NOT NECESSARY	49.00	-
1	REAR DOOR HINGE RH (LOWER) (CONSISTENT)	TWISTED	49.00	49.00
1	REAR DOOR CHECK RH (CONSISTENT)	TWISTED	46.00	46.00
1	REAR DOOR RH TRIM BOARD (CONSISTENT)	NOT NECESSARY	435.00	-
1	REAR DOOR RH WEATHERSTRIP (CONSISTENT)	NECESSARY	139.00	139.00
1	RH CENTRE DOOR PILLAR (CONSISTENT)	TO REPAIR SEE LABOUR	845.00	-
1	FRONT DOOR RH HANDLE (OUTER) (CONSISTENT)	NOT NECESSARY	89.00	-
1	FRONT DOOR RH LOCK ASSEMBLY (CONSISTENT)	NOT NECESSARY	239.00	-
1	REAR DOOR RH LOCK ASSEMBLY (CONSISTENT)	NOT NECESSARY	239.00	-
	LESS 10% DISCOUNT		-	-104.50
			4,774.00	940.50
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR DOOR TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	RH REAR DOOR ELECTRICAL WIRE HARNESS (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
1	SET FRONT DOOR TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	RH FRONT DOOR ELECTRICAL WIRE HARNESS (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
			440.00	-
<u>LABOUR</u>				
	TO CARRY OUT ANTI-RUST TREATMENT.		120.00	40.00
	REWIRING TO FACILITATE WORKS.		120.00	20.00

Report Ref No. CS/ASM23000262/Uvp3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER OF REAR DOOR MECHANISM.		280.00	60.00
	LABOUR TO REMOVE AND REPLACE DAMAGED PARTS (INCLUDING REFITTING AND REPOSITIONING OF REPLACED PARTS) INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND RH CENTRE DOOR PILLAR.		800.00	500.00
	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK.		900.00	600.00
			2,220.00	1,220.00
GRAND TOTAL			7,434.00	2,160.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS/ASM23000262/Uvp3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.