

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunios Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS23000266/AWY3Q2**Date:** 17/04/2023**REFERENCE**

Insured/Claimant: TOO TEH HSIN Policy No: MPC22A00148500
Date of Loss: 07/01/2023 Nature of Claim: OD Claim No: DMPC2300014H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY2513Z**
Make & Model: TOYOTA WISH, 2.0 (A) Engine No: 3ZRA491776
Reg. Date: 16/08/2010 (Man. Year: 2010) Chassis No: JTDGJ20W305002551
Colour: Blue Odometer: 174942 km
Engine Capacity: 1987 cc
Market Value/New Car Price: S\$26,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,360.30	4,453.90	906.40	16.91
Miscellaneous Items	140.00	70.00	70.00	50.00
Labour	1,050.00	930.00	120.00	11.43
Paintwork Labour	980.00	900.00	80.00	8.16
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,530.30	6,353.90	1,176.40	15.62
+ GST 8.00/8.00% (S\$)	602.42	508.31	94.11	15.62
Nett Amount (S\$)	8,132.72	6,862.21	1,270.51	15.62

INSPECTION

Date of Assignment: 09/01/2023 Present Location: Kan Fook Sing Motor Workshop (Defu)
Kan Fook Sing Motor Workshop (Defu)
Date Inspected: 11/01/2023 Inspected At: Blk 8 Defu South Street 1, Defu Industrial City #04-29
Singapore 533758
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Apr 2023)	
Parts:	N/A	TOYOTA WISH 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY2513Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	300.00 F	*300.00 F
2	1		*FRONT BONNET LOCK (WCP)	Damaged	40.00 F	*40.00 F
3	1		*FRONT BONNET HINGE RH (WCP)	Bent	35.00 F	*35.00 F
4	1		*FRONT BONNET HINGE L H (WCP)	Bent	35.00 F	*35.00 F
5	1		*FRONT BONNET INSULATOR (WCP)	Torn	160.00 F	*160.00 F
6	10		*FRONT BONNET INSULATOR CLIP (WCP)	Necessary	25.00 F	*9.00 F
7	1		*FRONT SUPPORT PANEL (WCP)	Buckled	480.00 F	*480.00 F
8	1		*FRONT SUPPORT TOP GARNISH (WCP)	Not Necessary	45.00 F	*- F
9	8		*FRONT SUPPORT TOP GARNISH CLIP (WCP)	Necessary	20.00 F	*20.00 F
10	1		*FRONT BRACE PANEL (WCP)	Bent	40.00 F	*40.00 F
11	1		*FRONT GRILLE (WCP)	Cracked	75.00 F	*75.00 F
12	1		*FRONT FENDER RH (WCP)	Dented	260.00 F	*260.00 F
13	1		*FRONT FENDER LH (WCP)	Buckled	260.00 F	*260.00 F
14	1		*FRONT FENDER SHIELD RH (WCP)	Deformed	80.00 F	*80.00 F
15	1		*FRONT FENDER SHIELD LH (WCP)	Not Necessary	80.00 F	*- F
16	20		*FRONT FENDER SHIELD CLIP (WCP)	Not Necessary	50.00 F	*- F
17	1		*FRONT HEADLAMP RH (WCP)	Cracked	330.00 F	*330.00 F
18	1		*FRONT HEADLAMP LH (WCP)	Cracked	330.00 F	*330.00 F
19	1		*FRONT BUMPER (WCP)	Distorted	280.00 F	*280.00 F
20	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Damaged	30.00 F	*30.00 F
21	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Damaged	30.00 F	*30.00 F
22	1		*FRONT BUMPER FOAM (WCP)	Cracked	40.00 F	*40.00 F
23	1		*FRONT BUMPER REINFORCEMENT (WCP)	Distorted	110.00 F	*110.00 F
24	1		*FRONT BUMPER FOGLAMP COVER LH (WCP)	Not Necessary	40.00 F	*- F
25	1		*FRONT BUMPER FOGLAMP INNER GRILLE LH (WCP)	Deformed	40.00 F	*35.00 F
26	10		*FRONT BUMPER CLIP (WCP)	Necessary	25.00 F	*25.00 F
27	1		*AIR CON CONDENSER (WCP)	Warped	270.00 F	*80.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*AIR CON SIDE GARNISH RH (WCP)	Not Necessary	35.00 F	*- F
29	1		*AIR CON SIDE GARNISH LH (WCP)	Not Necessary	35.00 F	*- F
30	1		*RADIATOR (WCP)	Dented	480.00 F	*160.00 F
31	1		*RADIATOR TOP HOSE (WCP)	Damaged	28.00 F	*20.00 F
32	1		*RADIATOR FAN COWLING (WCP)	Cracked	90.00 F	*90.00 F
33	1		*RADIATOR FAN BLADE (WCP)	Cut	65.00 F	*65.00 F
34	1		*RADIATOR FAN MOTOR (WCP)	Damaged	170.00 F	*170.00 F
35	1		*RADIATOR TOP GARNISH (WCP)	Cracked	40.00 F	*40.00 F
36	1		*SPARE TANK (WCP)	Deformed	75.00 F	*75.00 F
37	1		*WASHER TANK (WCP)	Deformed	45.00 F	*45.00 F
Supplementary #1						
38	1		*AIR CON FAN BLADE (WCP)	Damaged	80.00 F	*80.00 F
39	1		*AIR CON FAN MOTOR (WCP)	Damaged	165.00 F	*165.00 F
Supplementary #2						
40	1		*FRONT BUMPER FOG LAMP INNER GRILLE RH (WCP)	Deformed	35.00 F	*35.00 F
41	1		*RADIATOR LOWER HOSE (WCP)	Damaged	20.00 F	*20.00 F
F=Franchise part.						
					Sub Total (\$)	4,873.00 4,049.00
					+ Margin on L,N Items 10.00/10.00% (\$)	487.30 404.90
					Total Parts (\$)	5,360.30 4,453.90
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ALARM (CRACKED)	100.00	30.00
2	1	FRONT NUMBER PLATE (BENT)	40.00	40.00
Sub Total (S\$)			140.00	70.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	980.00	900.00
Labour Items				
2	TO CHECK WIING SYSTEM	New	50.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	120.00	100.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	880.00	800.00
Gross Labour Cost (S\$)			2,030.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >