



簡福星嘜王廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: -
Vehicle Reg. No.: SJY2513Z
Driver Age/Info:
TP Injury Involved? NO
Insured/Claimant: TOO TEH HSIN

Ref. No:
Date of Loss: 07/01/2023
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA WISH, 2.0 (A)
Vehicle Colour: METALLIC BLUE
Engine No: 3ZRA491776
Odometer: 0 KM

Vehicle Reg. Date: 16/08/2010
Chassis No: JTDGJ20W305002551

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 10

Present Location: KAN FOOK SING MOTOR WORKSHOP (DEFU)

COST OF CLAIMS

	Amount
Parts	5,030.30
Miscellaneous Items	140.00
Labour	1,050.00
Paintwork Labour	980.00
Towing	0.00
Gross Total (S\$)	7,200.30
+ GST 8.00% (S\$)	576.02
Nett Amount (S\$)	7,776.32

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Jan 2023)	
Parts:	N/A	TOYOTA WISH 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET <i>Deled</i>	0.00	0.00	*300.00 F	✓
2	1		*FRONT BONNET LOCK <i>Be?</i>	0.00	0.00	*40.00 F	?
3	1		*FRONT BONNET HINGE RH <i>} Best</i>	0.00	0.00	*35.00 F	✓
4	1		*FRONT BONNET HINGE L H <i>} Best</i>	0.00	0.00	*35.00 F	✓
5	1		*FRONT BONNET INSULATOR <i>new</i>	0.00	0.00	*160.00 F	✓
6	10		*FRONT BONNET INSULATOR CLIP <i>new</i>	0.00	0.00	*25.00 F	✓
7	1		*FRONT SUPPORT PANEL <i>Bruch</i>	0.00	0.00	*480.00 F	✓
8	1		*FRONT SUPPORT TOP GARNISH <i>Deled</i>	0.00	0.00	*45.00 F	✓
9	8		*FRONT SUPPORT TOP GARNISH CLIP <i>new</i>	0.00	0.00	*20.00 F	✓
10	1		*FRONT BRACE PANEL <i>Best</i>	0.00	0.00	*40.00 F	✓
11	1		*FRONT GRILLE <i>could</i>	0.00	0.00	*75.00 F	✓
12	1		*FRONT FENDER RH <i>Deled</i>	0.00	0.00	*260.00 F	✓
13	1		*FRONT FENDER LH <i>Bruch</i>	0.00	0.00	*260.00 F	✓
14	1		*FRONT FENDER SHIELD RH <i>} new</i>	0.00	0.00	*80.00 F	+
15	1		*FRONT FENDER SHIELD LH <i>} new</i>	0.00	0.00	*80.00 F	+
16	20		*FRONT FENDER SHIELD CLIP <i>} new</i>	0.00	0.00	*50.00 F	+
17	1		*FRONT HEADLAMP RH <i>} could</i>	0.00	0.00	*330.00 F	✓
18	1		*FRONT HEADLAMP LH <i>} could</i>	0.00	0.00	*330.00 F	✓
19	1		*FRONT BUMPER <i>Deled</i>	0.00	0.00	*280.00 F	✓
20	1		*FRONT BUMPER SIDE RETAINER RH <i>?</i>	0.00	0.00	*30.00 F	?
21	1		*FRONT BUMPER SIDE RETAINER LH <i>?</i>	0.00	0.00	*30.00 F	?
22	1		*FRONT BUMPER FOAM <i>could</i>	0.00	0.00	*40.00 F	✓
23	1		*FRONT BUMPER REINFORCEMENT <i>Disheled</i>	0.00	0.00	*110.00 F	✓
24	1		*FRONT BUMPER FOGLAMP COVER LH <i>} new</i>	0.00	0.00	*40.00 F	+
25	1		*FRONT BUMPER FOGLAMP INNER GRILLE LH <i>} new</i>	0.00	0.00	*40.00 F	+
26	10		*FRONT BUMPER CLIP <i>new</i>	0.00	0.00	*25.00 F	✓
27	1		*AIR CON CONDENSER <i>Warpped</i>	0.00	0.00	*270.00 F	✓
28	1		*AIR CON SIDE GARNISH RH <i>?</i>	0.00	0.00	*35.00 F	?
29	1		*AIR CON SIDE GARNISH LH <i>?</i>	0.00	0.00	*35.00 F	?
30	1		*RADIATOR <i>?</i>	0.00	0.00	*480.00 F	?
31	1		*RADIATOR TOP HOSE <i>?</i>	0.00	0.00	*28.00 F	?
32	1		*RADIATOR FAN COWLING <i>?</i>	0.00	0.00	*90.00 F	?
33	1		*RADIATOR FAN BLADE <i>?</i>	0.00	0.00	*65.00 F	?
34	1		*RADIATOR FAN MOTOR <i>?</i>	0.00	0.00	*170.00 F	?
35	1		*RADIATOR TOP GARNISH <i>?</i>	0.00	0.00	*40.00 F	?
36	1		*SPARE TANK <i>Deled</i>	0.00	0.00	*75.00 F	✓
37	1		*WASHER TANK <i>new</i>	0.00	0.00	*45.00 F	✓

F=Franchise part.

Sub Total (\$\$)	4,573.00
+ Margin on L,N Items 10.00% (\$\$)	457.30
Total Parts (\$\$)	5,030.30

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	ALARM	100.00
2	1	FRONT NUMBER PLATE <i>Best</i>	40.00
Sub Total (S\$)			140.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	980.00 <i>900</i>
<u>Labour Items</u>			
2	TO CHECK WIING SYSTEM	New	50.00 <i>30</i>
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	120.00 <i>100</i>
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	880.00 <i>800</i>
Gross Labour Cost (S\$)			2,030.00

Kan Fook Sing Motor Workshop/SJY2513Z/09/01/2023 15:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian G

P/P 11/01/23

07 Days.

Not Authorized

Excess \$600