



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JUS 1416

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	R/L FRONT FORK ASSY	BENT	780.00	780.00
1	FRONT SPOLING ASSY	CRACKED	395.00	395.00
1	FRONT BRAKE DISD	CRACKED	195.00	195.00
1	RIM SHAFT	NECESSARY	48.00	48.00
1	FRONT FORK UNDER BRACKET	BENT	380.00	380.00
1	CONE BEARING ASSY	BENT	130.00	130.00
1	FRONT MUDGUARD	CRACKED	98.00	98.00
1	HANDLE BAR ASSY	BENT	145.00	145.00
2	HANDLE GRIP R/L	MISSING	38.00	38.00
2	R/L HANDLE BAR BELESEN	SCRATCHED	58.00	58.00
1	HEAD LIGHT ASSY	BROKEN	480.00	480.00
2	HEAD COWING R/L	CRACKED	490.00	490.00
1	HEAD COWING CENTRE WINKIM	CRACKED	295.00	295.00
2	FRONT MIRRLE R/L	CRACKED	190.00	190.00
1	WISKIM R/L COVER	SCRATCHED	48.00	48.00
2	BRAKE LEVER R/L	SCRATCHED	130.00	130.00
2	SIGNAL FRONT R/L	CRACKED	190.00	190.00
1	CHASSIS BODY ASSY	BENT	1,950.00	1,950.00
1	METER ASSY	CRACKED	595.00	595.00
1	METER COVER	CRACKED	95.00	95.00
1	(BLACK) - WISKIM IN COVER	SCRATCHED	168.00	168.00
1	FRONT CENTRAL BRACKET	BENT	295.00	295.00
1	RADIATOR ASSY	BENT	490.00	490.00
1	RADIATOR COVER	BENT	85.00	85.00
1	HANDLE BAR LOWER COVER	CRACKED	95.00	95.00
1	FAN & METER ASSY	CRACKED	380.00	380.00
1	BODY CENTRAL COVER BIG	CRACKED	295.00	295.00
1	KEY CENTRAL COVER	CRACKED	155.00	155.00
1	(L) TOOL BOX COVER	CRACKED	58.00	58.00
1	SEAT FRONT COVER	CRACKED	145.00	145.00
2	R/L HEAD LIGHT CENTRAL COVER	CRACKED	190.00	190.00

Report Ref No. CS/AGI23000270/Rqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
5	LOWER FAILING ASSY	CRACKED	690.00	690.00
1	UNDER FAILING	CRACKED	195.00	195.00
6	SIDE FAILING R/L	CRACKED	850.00	850.00
2	FRONT FOOT REST COVER R/L	SCRATCHED	360.00	360.00
1	SIDE STEM	BENT	135.00	135.00
1	MISTER ASSY	BENT	155.00	155.00
1	(L) BEITING BOX COVER	SCRATCHED	95.00	95.00
1	(L) REAR SIDE FAILING	CUT	295.00	295.00
1	ABS SENSOR FRONT	CUT	85.00	85.00
1	(BLUE)-CENTRAL BODY FAILING R/L	NOT NECESSARY	290.00	-
1	AJER PIPE ASSY	BENT	590.00	590.00
1	REAR KAPPAL BOX	SCRATCHED	165.00	165.00
	LESS 10% DISCOUNT		-	-1,270.10
			12,991.00	11,430.90
	<u>SPECIAL NETT ITEMS</u>			
1	NOMBOR PLATE FRONT (SN)	BENT	28.00	20.00
			28.00	20.00
	<u>LABOUR</u>			
	TOWING TO TP.		60.00	60.00
	LABOUR.		380.00	300.00
			440.00	360.00
	GRAND TOTAL		13,459.00	11,810.90
	RECOMMENDED COST OF REPAIRS			11,810.90

Report Ref No. CS/AGI23000270/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.