

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23000275/KQY3E2**Date:** 10/04/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001915128
Claimant Vehicle No :	SLV4517S	Insured Vehicle No :	SP71K
Date of Loss:	10/12/2022	Nature of Claim:	TP
		Claim No:	294712

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV4517S	Engine No:	B104J446N13B16A
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Chassis No:	WBA3A16050NP99443
Reg. Date:	19/06/2013 (Man. Year: 2013)	Odometer:	143160 km
Colour:	Metallic Pearl White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,722.66	1,125.51	1,597.15	58.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	510.00	270.00	34.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,502.66	1,635.51	1,867.15	53.31
+ GST 8.00/8.00% (S\$)	280.21	130.84	149.37	53.31
Nett Amount (S\$)	3,782.87	1,766.35	2,016.52	53.31

INSPECTION

Date of Assignment:	10/01/2023	
Date Inspected:	10/01/2023	Inspected At: 160 Sin Ming Drive #03-09 Sin Ming Autocare
Estimated Period of Repair:	2.0 days	Repairer: Bifrost Auto Pte Ltd (HQ)

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2023)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4517S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	1,384.55 F	*1,184.75 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	577.45 F	*- FL
3	1		*REAR BUMPER LOWER GARNISH	Serviceable	189.56 F	*- FL
4	2		*REAR BUMPER SENSOR	Serviceable	571.10 F	*- FL
					Sub Total (S\$)	2,722.66 1,184.75
					- List Item Discount on L Items 0.00/5.00% (S\$)	0.00 59.24
					Total Parts (S\$)	2,722.66 1,125.51

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	300.00	200.00
2	CHECK REAR WIRING & REPLACE SENSOR	New	80.00	60.00
3	SPRAY PAINTING CHARGE	New	400.00	250.00
Gross Labour Cost (\$\$)			780.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >