

ASS. REC. BY:

REF:

SPF / 230002761/Kny3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBL 7982H

Yr Regn:

04.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hiace

c.c

1998

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

18088

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TRH 200 0344430

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

31/12/22

D.O.I.

13/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No car yet.

15/3

1/Rep @ 17501 Car lot

(Red. \$1370.03, 44%)

Range @ 1.5-2.5k

Date/Time, File Pass to?

☐

: Prel. Report

1) 16/3/23

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

L H Express Motor Trading

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel: 91082728

Sing Onn Electrical Trading
Blk 87 Dawson Road
#24-29
Singapore 141087

Vehicle No: GBL 7982 H
Make/Model: Toyota Hiace
Year: 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc Rear n/s sliding door **1486.60**

Less 25 %

B1 \$1,546.70 ✓

\$386.67

\$1,160.03

S Nett

1 pc Rear n/s tyre hub cap **SVC**

\$100.00 X

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting etc.

\$800.00

400L

To putty and spray paint on rear accident portion.

\$800.00

600L

To respray anti-rust proofing treatment

\$100.00

30L

Check and reconnect wiring

\$40.00

15L

Remove/refit rear n/s sliding door mechanism to new door.

\$120.00

60L

Total

\$3,120.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kn

range

Not Authorized
11pm @ 1750h
Resurvey After Paint