



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 7982H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b><u>REPLACEMENT OF PARTS</u></b>	BENT	1,546.70	1,486.60
	REAR N/S SLIDING DOOR		-386.68	-371.65
	LESS 25% DISCOUNT		1,160.02	1,114.95
	<b><u>SPECIAL NETT ITEMS</u></b>	SERVICEABLE		
	REAR N/S TYRE HUB CAP (SN)		100.00	-
			100.00	-
	<b><u>LABOUR</u></b>			
	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING & CUTTING ETC.		800.00	400.00
	TO PUTTY AND SPRAY PAINT ON REAR ACCIDENT PORTION.		800.00	600.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.		100.00	30.00
	CHECK AND RECONNECT WIRING.		40.00	15.00
	REMOVE/REFIT REAR N/S SLIDING DOOR MECHANISM TO NEW DOOR.		120.00	60.00
			1,860.00	1,105.00
<b>GRAND TOTAL</b>			<b>3,120.02</b>	<b>2,219.95</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,750.00</b>

Report Ref No. CS/SPF23000276/Kny3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500**

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.