



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23000276/Kny3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	17/03/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 26Z	Veh. Inspected	GBL 7982H
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/114	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	09/01/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	TRH2000344430	Colour	WHITE
Odometer	18098 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	DUNLOP	8 mm
L/H Front Tyre	195 R15X8	DUNLOP	8 mm
R/H Rear Tyre	195 R15X8	DUNLOP	8 mm
L/H Rear Tyre	195 R15X8	DUNLOP	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/12/2022	Inspection Date	13/01/2023
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	