5/3/23, 2:16 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23000277/RNP3Q2

03/05/2023 Date:

**REFERENCE** 

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00076982204

**Claimant Vehicle** 

SMV5952A

Insured

Chassis No:

Odometer:

Vehicle No:

Nature of

SFE5151S

Date of Loss: 03/01/2023 Claim:

TP

Claim SNM23D200096/C02/TANCHC No:

WAUZZZF40MN000632

50632 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMV5952A Reg No:

Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A)

DEM025299 Engine No:

Colour: Grev

**Engine Capacity:** 

1984 cc

Market Value/New Car Price:

Reg. Date:

N/A

Sum Insured (S\$):

Market Value/New Car Price

10/10/2020 (Man. Year: 2020)

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17 Front Left Side: VENUS 6 mm Rear Left Side: VENUS 6 mm Front Right Side: VENUS 6 mm Rear Right Side: VENUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,270.10	2,252.30	2,017.80	47.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	440.00	750.00	63.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,460.10	2,692.30	2,767.80	50.69
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	5,460.10	2,150.00	3,310.10	60.62
+ GST 8.00/8.00% (S\$)	436.81	172.00	264.81	60.62
Nett Amount (S\$)	5,896.91	2,322.00	3,574.91	60.62

**INSPECTION** 

Date of Assignment: 27/04/2023

Wah Hong Motors & Credit Pte Ltd (HQ) Date Inspected: 11/01/2023 Inspected At:

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: **HUEY YON** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/3/23, 2:16 PM Adjuster Report

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 May 2023)

Parts: 143 AUDI A4 2.0 TFSI S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMV5952A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	2,334.00 FL	*2,334.00 FL
2	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	334.00 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	121.00 FL	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Not Necessary	601.00 FL	*- FL
5	4		*REAR REVERSE SENSOR	Not Necessary	1,068.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,493.00	2,369.00
	- List Item Discount on L Items 5.00/5.00% (S\$)				222.90	116.70
				Total Parts (S\$)	4,270.10	2,252.30
			Report was unsubmitted during	this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	600.00	200.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,& RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	400.00	200.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	0.00
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	100.00	40.00
5	TO REMOVE /REFIX /REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	0.00
	Gross Labour Cost (S\$)		1,190.00	440.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >