

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000279/UVP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00002752202		
Claimant Vehicle No :	SKS1760C	Insured Vehicle No :	SJM9664M		
Date of Loss:	06/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200172/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS1760C	Engine No:	1ZRX495487
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104528730
Reg. Date:	30/03/2015 (Man. Year: 2015)	Odometer:	84183 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,333.60	1,259.75	1,073.85	46.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	1,070.00	440.00	29.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,843.60	2,329.75	1,513.85	39.39
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	3,843.60	1,850.00	1,993.60	51.87
+ GST 8.00/8.00% (S\$)	307.49	148.00	159.49	51.87
Nett Amount (S\$)	4,151.09	1,998.00	2,153.09	51.87

INSPECTION

Date of Assignment:	13/01/2023		
Date Inspected:	14/02/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS1760C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	669.10 FL	*669.10 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*REAR BUMPER SIDE HOLDER -LH	Not Necessary	131.80 FL	*- FL
4	1		*REAR BUMPER SIDE HOLDER -RH	Bent	131.80 FL	*131.80 FL
5	1		*REAR BUMPER CENTRE BRACKET -LH	Not Necessary	81.90 FL	*- FL
6	1		*REAR BUMPER CENTRE BRACKET -RH	Dented	81.90 FL	*81.90 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	480.20 FL	*480.20 FL
8	1		*REAR BUMPER BRACKET -RH	Not Necessary	79.70 FL	*- FL
9	1		*REAR PANEL	Repair	808.00 FL	*- FL
10	1		*REAR PANEL TOP GARNISH	Not Necessary	290.40 FL	*- FL
11	1		*SET REAR BUMPER SENSOR	Shorted	230.00 FS	*200.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					3,034.80	1,613.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					701.20	353.25
Total Parts (\$\$)					2,333.60	1,259.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,CUT /WELD REAR PANEL ,REMOVE ,REPLACE ACCIDENT PARTS	New	600.00	500.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	700.00	500.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
5	TO TUFF-KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,510.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >