



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 1796A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP	CRACKED	385.00	385.00
	LESS 15% DISCOUNT		-	-57.75
			385.00	327.25
	<u>SPECIAL NETT ITEMS</u>			
1	TAIL LAMP BRACKET (SN)	BENT	600.00	450.00
1	REAR MUDGUARD (SN)	BENT	800.00	600.00
1	REAR MUDFLAT (SN)	TORN	50.00	50.00
1	REAR MUDGUARD BRACKET (SN)	BENT	230.00	230.00
1	REAR TYRE (450.00) (80%) (SN)	CUT	600.00	360.00
			2,280.00	1,690.00
	<u>LABOUR</u>			
	WIRING SERVICES.		80.00	30.00
	LABOUR CHARGES.		800.00	600.00
	PUTTY & SPRAY PAINTING.		500.00	300.00
			1,380.00	930.00
GRAND TOTAL			4,045.00	2,947.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/SMR23000293/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.