

S. REC BY: T. J. P. M.REF: CS/3mk23000293/T9y3-

ASSIGNMENT

2027 Aug:

20071 Sep

From: _____ Date: _____

Veh No: XD17964 Yr Regn: 20071 Sep

Estimated cost: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TR / VS / TPRES / OD RES / EVA / INV / MVTruck / Trailer or Tipper - truck

To inspect Vehicle No: _____

Make: Isuzu CYZ52L C.C. 15681

at Workshop T/s _____

Colour: Blue/Green A/C: Insured / Std / NI / NA

of _____

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No: _____

C/No: JAL CYZ52L 77 000097

Claims Nil: _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____

Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: W / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: _____

R: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

BS / DUN / EXNOVA / GY / FS / LZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or

Bal. or Market Value: \$58K.

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mm

D.O.A. _____

D.O.L. 17/1/230/2pmSurvey held at Lee Kuen HW.

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + 95.81

Photos

Other

Paper Form: _____

Lump Sum / L.S. (\$)

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Tel: 6269 9192 H/P: 9631 1712

Business Reg. No: 36463500B

M/s: MS FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877

Date : 17.01.2023

Motor Claim Dept

Vehicle number : XD 1796 A
Make/Model : ISUZU CYZ
Date of accident : 03.11.2022
Claim Type : TP Claim

Accident involving XD 1796 A & SHD 6078 X

Re: Estimate

1. 1 PC TAIL LAMP
2. 1 PC TAIL LAMP BRACKET
3. 1 PC REAR MUDGUARD
4. 1 PC REAR MUDFLAT
5. 1 PC REAR MUDGUARD BRACKET
6. 1 PC REAR TYRE

LKK Auto Cons. is hereby
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 385.00 *an*
\$ 600.00 *bb*
\$ 800.00 *bb*
\$ 50.00 *tn*
\$ 230.00 *lt*
\$ 600.00 *ab* *80%*

\$ 2,665.00

ISUZU DISCOUNT -15%

\$ 399.75

SUB TOTAL

\$ 2,265.25

WIRING SERVICES

\$ 80.00 *30*

LABOUR CHARGES

\$ 800.00 *600*

PUTTY & SPRAY PAINTING

\$ 500.00 *300*

Yours Faithfully,

TOTAL

\$ 3,645.25

李光華 摩哆燒焊

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

Taufik 97495749/62563561
ur 17/1/23 @ 12pm
L/S Resurvey after repair
taufik@khanh.com
3-4 days