

REC BY: [Signature] REF: CS/3mk23000293/T943-

ASSIGNMENT

2027 Aug:
2007 Sep

On: _____ Date: _____
Submitted to: _____
To: IB / VS / TPRES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
At Workshop no: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: \$58k.
D.A.C. Accident Rpt: _____ Consistent? : Yes or No
SIA / PR Seal: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
A / REV / REP. / 24 HRS
Date: _____ Person Contacted: Adeline
Vehicle: IN / OUT

N/S	O/S

Veh No: XD17964 Yr Regn: 2007 Sep
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or Tipper-truck
Make: Isuzu CYZ52L C.D. 15681
Colour: Blue/Green A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JAL CYZ52L 77 000047
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: W / S/Rim / STD A/Rim or
Tyre Size: F: 245/80 R22.5
R: ~ ~ (D)
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO, DI BYCROSS
Front Rear
R/Bal. 8 mm R/Bal. 8/8 mm
L/Bal. 8 mm L/Bal. 8/8 mm
D.O.A. _____ D.O.L. 17/1/230/2pm
Survey held at Lee Kuan Hwa
Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>5/6/23</u>	<u>Finalised LS \$2350f; 3 days with Adeline. (Red 1695f, 42%)</u>

Site/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
Site/Time, File Return to?
Days Of Repair: 3
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)
Survey Fee: _____
Transportation: \$ + \$5.00
Photos: _____
Other: _____
Report Form: TP
Turn Sum / L.B.R. / \$2350f

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Tel: 6269 9192 H/P: 9631 1712

Business Reg. No: 36463500B

M/s: MS FIRST CAPITAL INSURANCE LTD

36 Robinson Road

#16-01 City House

Singapore 068877

Date: 17.01.2023

Motor Claim Dept

Vehicle number : XD 1796 A

Make/Model : ISUZU CYZ

Date of accident : 03.11.2022

Claim Type : TP Claim

Accident involving XD 1796 A & SHD 6078 X

Re: Estimate

1. 1 PC TAIL LAMP 15%
2. 1 PC TAIL LAMP BRACKET
3. 1 PC REAR MUDGUARD
4. 1 PC REAR MUDFLAT
5. 1 PC REAR MUDGUARD BRACKET
6. 1 PC REAR TYRE

LKK Auto Const. is hereby
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 385.00 *over*
\$ 600.00 *bb*
\$ 800.00 *bb*
\$ 50.00 *th*
\$ 230.00 *lt*
\$ 450 600.00 *ab* *80% 360*

ISUZU DISCOUNT -15%

\$ 2,665.00
\$ 399.75

SUB TOTAL

\$ 2,265.25

WIRING SERVICES

LABOUR CHARGES

PUTTY & SPRAY PAINTING

\$ 80.00 *30*
\$ 800.00 *600*
\$ 500.00 *300*

Yours Faithfully,

TOTAL

\$ 3,645.25
4,045.00

李光華 摩 嘢 燒 焊

LEE KUAN HWA MOTOR SERVICE

39, Westwood Avenue, Singapore 648719

TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

Tanpin 9749574 9/62563561
at 17/1/23 @ 12pm
L/S Resurvey after repair
Tanpin C/Khantun n
3-4 days.