

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7895H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	420.00	-
1	FRONT LH FENDER WHEEL ARCH	SCRATCHED	100.00	100.00
1	FRONT LH DOOR	BUCKLED	1,150.00	1,150.00
1	SET FRONT LH DOOR FRAME STICKER	NECESSARY	80.00	80.00
2	FRONT LH DOOR HINGE	NOT NECESSARY	160.00	-
1	FRONT LH DOOR CHECKER	NOT NECESSARY	85.00	-
1	FRONT LH DOOR HANDLE	NOT NECESSARY	265.00	-
1	FRONT LH DOOR HANDLE SMALL COVER	NOT NECESSARY	105.00	-
1	REAR LH DOOR	BENT	1,150.00	1,150.00
1	SET REAR LH DOOR FRAME STICKER	NECESSARY	80.00	80.00
1	LH SIDE SKIRT	SCRATCHED	380.16	380.16
	LESS 20% DISCOUNT		-795.03	-588.04
			3,180.13	2,352.12
	SPECIAL NETT ITEMS			
1	SET FENDER SHIELD CLIPS (SN)	NOT NECESSARY	35.00	-
1	SET BUMPER CLIPS (SN)	NOT NECESSARY	35.00	-
1	SET DOOR INNER COMPARTMENT CLIPS (SN)	NECESSARY	35.00	35.00
			105.00	35.00
	<u>LABOUR</u>			
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,000.00	600.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT, WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER.		800.00	600.00
	CHECK WIRING SYSTEM & LIGHT.	NOT NECESSARY	100.00	-
	ANTI RUST TREATMENT.		120.00	60.00
	TO REMOVE & REFIX FRONT & REAR LH DOOR INNER COMPARTMENT TO FACILITATE REPAIR.		360.00	120.00
			2,380.00	1,380.00
	GRAND TOTAL		5,665.13	3,767.12

Report Ref No. CS/INC23000303/Rqy3e2



Page No.:2 of 2

## RECOMMENDED COST OF REPAIRS (CONFIRMED) 3,767.12

Report Ref No. CS/INC23000303/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

M

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**