



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9025R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	COVER, RR BUMPER (SN)	DEFORMED	669.10	568.73
1	REINFORCEMENT SUB-AS (SN)	BENT	480.20	408.17
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	72.80	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	72.80	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	131.80	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	131.80	-
1	SEAL, RR BUMPER SIDE (SN)	NOT NECESSARY	66.30	-
1	SEAL, RR BUMPER SIDE (SN)	NOT NECESSARY	66.30	-
10	PIECE, RR BUMPER @\$5.40 (SN)	NECESSARY	54.00	41.60
1	PANEL SUB-ASSY, BODY (SN)	NOT NECESSARY	808.00	-
1	PANEL SUB-ASSY, LUGG (SN)	BENT	947.10	805.03
1	WEATHERSTRIP, LUGGAG (SN)	NOT NECESSARY	211.10	-
1	ARM SUB-ASSY, LUG CO (SN)	NOT NECESSARY	83.90	-
1	ARM SUB-ASSY, LUG CO (SN)	NOT NECESSARY	83.90	-
1	PLATE, RR FLOOR FINI (SN)	DEFORMED	290.40	246.84
1	BACK SENSOR 1F9 310A (SN)	NOT NECESSARY	160.10	-
1	GARNISH SUB-ASSY, BA (SN)	NOT NECESSARY	292.50	-
1	EMBLEM, LUGGAGE COMP (SN)	NECESSARY	74.20	63.07
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	49.30	41.90
1	PLATE, LUGGAGE (SN)	NECESSARY	54.80	46.58
1	LAMP ASSY, RR, RH (SN)	NOT NECESSARY	473.80	-
1	LAMP ASSY, RR, LH (SN)	NOT NECESSARY	473.80	-
1	LAMP ASSY, RR COMBIN (SN)	NOT NECESSARY	456.10	-
1	LAMP ASSY, RR COMBIN (SN)	NOT NECESSARY	456.10	-
1	LAMP ASSY, LICENSE (SN)	NOT NECESSARY	78.60	-
1	REFLECTOR ASSY, REFL (SN)	NOT NECESSARY	72.20	-
1	REFLECTOR ASSY, REFL (SN)	NOT NECESSARY	72.20	-
			6,983.20	2,251.92

Report Ref No. CS/INC23000304/Rqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	CHECK WIRING AND CONDUCT LEAK TEST.		198.00	198.00
	TO RESET ECU AND REPROGRAMME.		198.00	198.00
	DRILL HOLE AND INSTALL REVERSE SENSOR.		198.00	198.00
	REMOVE INTERIOR UPHOLSTERY TO FAC TO REP AIR.		792.00	396.00
	REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA.		3,960.00	3,168.00
	RESPRAY ACC AFF AREA.		3,936.00	1,968.00
			9,282.00	6,126.00
	GRAND TOTAL		16,265.20	8,377.92
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			8,377.92

Report Ref No. CS/INC23000304/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.