



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 2958Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	GLASS SUB-ASSY, FR (SN)	SCRATCHED	977.00	830.45
1	FRAME SUB-ASSY, FR (SN)	SCRATCHED	173.30	147.30
1	GLASS, FR DOOR FIX (SN)	MISSING	383.90	326.31
1	MIRROR ASSY, OUTER (SN)	CRACKED	1,727.70	1,468.54
1	COVER, OUTER MIRROR (SN)	MISSING	130.70	111.09
1	FRAME SUB-ASSY, FR (SN) (ADDITIONAL)	REPEATED	147.30	-
1	RUN, FR DOOR GLASS (SN) (ADDITIONAL)	CUT	148.49	148.49
			3,788.39	3,062.18
	<u>LABOUR</u>			
	CHECK WIRING AND CONDUCT LEAK TEST.		198.00	198.00
	TO RESET ECU AND REPROGRAMME.		198.00	198.00
	R/I FRONT RIGHT DOOR COMPARTMENT.	NOT NECESSARY	792.00	-
	REPL ACC AFF AREA. STRAIGHTEN AND PANEL ACC AFF AREA.		2,376.00	792.00
	RESPRAY ACC AFF AREA.		3,936.00	854.00
			7,500.00	2,042.00
	GRAND TOTAL		11,288.39	5,104.18
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			5,104.18

Report Ref No. CS/INC23000306/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.