

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG23000307/TQCE2**Date:** 08/06/2023**REFERENCE**

Insured/Claimant:	NAVPREET PUAR	Policy No:	7220147693	
Date of Loss:	03/01/2023	Nature of Claim:	OD	Claim No: 1233529883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW8335C		
Make & Model:	AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A)	Engine No:	HIDDEN
Reg. Date:	16/12/2022 (Man. Year: 2022)	Chassis No:	WAUZZZGE5PB000624
Colour:	Blue	Odometer:	1295 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$290,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,328.00	5,930.48	23,397.52	79.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,802.00	2,402.00	4,400.00	64.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,130.00	8,332.48	27,797.52	76.94
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	35,530.00	7,732.48	27,797.52	78.24
+ GST 8.00/8.00% (S\$)	2,842.40	618.60	2,223.80	78.24
Nett Amount (S\$)	38,372.40	8,351.08	30,021.32	78.24

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	06/01/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	2,896.00 FS	*2,316.80 FS
2	2		*FRONT BUMPER TRIM - LH / RH	Not Necessary	130.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	658.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Cracked	248.00 FS	*198.40 FS
5	1		*FRONT BUMPER FOAM PART - LH	Not Necessary	34.00 FS	*- FS
6	2		*FRONT BUMPER SUPPORT COVER - LH / RH	Not Necessary	78.00 FS	*- FS
7	1		*FRONT BUMPER FOAM PART - UPPER	Cracked	150.00 FS	*120.00 FS
8	1		*FRONT BUMPER FOAM PART - LOWER	Not Necessary	125.00 FS	*- FS
9	1		*FRONT BUMPER PLASTIC FOAM STRIP	Not Necessary	134.00 FS	*- FS
10	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	283.00 FS	*226.40 FS
11	1		*FRONT BUMPER GRILLE - CENTER	Cracked	171.00 FS	*136.40 FS
12	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	235.00 FS	*- FS
13	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	202.00 FS	*- FS
14	1		*FRONT BUMPER IMPACT PROTECTION	Not Necessary	899.00 FS	*- FS
15	2		*FRONT BUMPER SPOILER - LH / RH	Not Necessary	220.00 FS	*- FS
16	2		*FRONT BUMPER AIR GUIDE - LH / RH OUTER	Not Necessary	116.00 FS	*- FS
17	2		*FRONT BUMPER AIR GUIDE - LH / RH INNER	Not Necessary	90.00 FS	*- FS
18	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	268.00 FS	*- FS
19	1		*RADIATOR GRILLE	Cracked	2,317.00 FS	*1,853.60 FS
20	1		*RADIATOR GRILLE COVER CAP	Not Necessary	141.00 FS	*- FS
21	1		*RADIATOR GRILLE BRACKET	Not Necessary	104.00 FS	*- FS
22	1		*RADIATOR GRILLE COVER	Not Necessary	69.00 FS	*- FS
23	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	246.00 FS	*- FS
24	2		*RADIATOR GRILLE COVER - LH / RH	Not Necessary	122.00 FS	*- FS
25	1		*FRONT 360 CAMERA	Not Necessary	1,006.00 FS	*- FS
26	1		*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
27	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,451.00 FS	*- FS
28	1		*FRONT BUMPER SUPPORT BRACKET	Not Necessary	481.00 FS	*- FS
29	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	174.00 FS	*- FS
30	1		*FRONT BUMPER SIGHT SHIELD	Not Necessary	118.00 FS	*- FS
31	1		*FRONT BUMPER SIGHT SHIELD	Not Necessary	119.00 FS	*- FS
32	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	50.00 FS	*- FS
33	1		*CAUTION LABEL	Not Necessary	23.00 FS	*- FS
34	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	584.00 FS	*- FS
35	1		*FRONT PARKING AID SENSOR - OUTER	Cracked	292.00 FS	*233.20 FS
36	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
37	2		*FRONT SPOILER - LH / RH	Not Necessary	212.00 FS	*- FS
38	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	598.00 FS	*- FS
39	2		*RADIATOR AIR GUIDE BRAKE - LH / RH	Not Necessary	100.00 FS	*- FS
40	1		*FRONT FENDER - LH	Not Necessary	2,477.00 FS	*- FS
41	1		*FRONT FENDER BRACKET - LH	Not Necessary	11.00 FS	*- FS
42	1		*FRONT FENDER BRACKET - CENTRE LH	Not Necessary	15.00 FS	*- FS
43	1		*FRONT FENDER BRACKET - REAR	Not Necessary	15.00 FS	*- FS
44	1		*FRONT FENDER BRACKET - LH	Not Necessary	76.00 FS	*- FS
45	1		*FRONT FENDER BRACKET - LH INNER	Not Necessary	18.00 FS	*- FS
46	1		*HEADLIGHT SEAL - LH	Not Necessary	60.00 FS	*- FS
47	1		*FRONT SUPPORT ELEMENT - LH	Not Necessary	45.00 FS	*- FS
48	1		*HEADLIGHT - LH	Not Necessary	8,660.00 FS	*- FS
49	2		*FRONT WHEEL COVER - LH / RH	Cracked	648.00 FS	*517.60 FS
50	2		*LIFT CYLINDER - LH / RH	Not Necessary	518.00 FS	*- FS
51	1		*LIFT CYLINDER HOSE	Not Necessary	111.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
53	1		*SUNDRIES	Necessary	500.00 FS	*14.48 FS
54	1		*LICENCE PLATE HOLDER (Supplementary)	Cracked	229.00 FS	*182.80 FS
55	1		*RADIATOR AIR GUIDE - UPPER (Supplementary)	Cracked	89.00 FS	*70.80 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					29,328.00	5,930.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	0.00
3	TO CARRY OUT DE-ENERGISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACIVATION	New	480.00	480.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	600.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,802.00	2,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >