

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123000308/AWY3Q2**Date:** 17/05/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJM9664M **Insured Vehicle No :** SLQ9660D

Date of Loss: 06/01/2023 Nature of Claim: TP Claim No: CDMPG23000034

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM9664M**

Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A1791962

Reg. Date: 22/01/2009 (Man. Year: 2008) Chassis No: RN61082880

Colour: Black Odometer: 289151 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,707.44	6,564.00	11,143.44	62.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,510.00	3,550.00	3,960.00	52.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,217.44	10,114.00	15,103.44	59.89
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	25,217.44	8,000.00	17,217.44	68.28

INSPECTION

Date of Assignment: 11/05/2023

Date Inspected: 10/01/2023 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM9664M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	688.40 FL	*688.40 FL
2	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	70.40 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	296.70 FL	*296.70 FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	145.40 FL	*- FL
5	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	130.40 FL	*- FL
6	1		*FRONT GRILLE	Cracked	259.40 FL	*259.40 FL
7	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	230.30 FL	*- FL
8	1		*FRONT GRILLE LOGO	Necessary	48.90 FL	*48.90 FL
9	1		*HEADLAMP	N/S Cracked	1,361.40 FL	*680.70 FL
10	1		*HEADLAMP LOWER BRACKET	N/S Cracked	91.80 FL	*45.90 FL
11	1		*BONNET	Repair	761.90 FL	*- FL
12	1		*BONNET LOCK	Not Necessary	98.10 FL	*- FL
13	2		*BONNET HINGE	Not Necessary	110.40 FL	*- FL
14	1		*BONNET INSULATOR	Not Necessary	162.40 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Not Necessary	566.50 FL	*- FL
16	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	167.40 FL	*- FL
17	2		*FRONT FENDER	Not Necessary	1,152.80 FL	*- FL
18	2		*HORN	Not Necessary	152.40 FL	*- FL
19	1		*AIR CON CONDENSER	Not Necessary	1,086.40 FL	*- FL
20	1		*AIR CON FAN COWLING	Not Necessary	129.60 FL	*- FL
21	1		*AIR CON FAN BLADE	Not Necessary	65.20 FL	*- FL
22	1		*AIR CON FAN MOTOR	Not Necessary	356.40 FL	*- FL
23	1		*RADIATOR	Not Necessary	1,284.40 FL	*- FL
24	1		*RADIATOR FAN COWLING	Not Necessary	139.20 FL	*- FL
25	1		*RADIATOR FAN BLADE	Not Necessary	66.10 FL	*- FL
26	1		*RADIATOR FAN MOTOR	Not Necessary	341.90 FL	*- FL
27	1		*RADIATOR SPARE TANK	Not Necessary	94.70 FL	*- FL
28	1		*RADIATOR TOP HOSE	Not Necessary	56.80 FL	*- FL
29	2		*REAR NUMBER PLATE LAMP	Not Necessary	124.40 FL	*- FL
30	1		*REAR BUMPER	Distorted	668.40 FL	*668.40 FL
31	1		*REAR BUMPER SIDE HOLDER	N/S Damaged	68.20 FL	*34.10 FL
32	1		*REAR BUMPER TOW COVER	Not Necessary	39.40 FL	*- FL
33	1		*REAR END PANEL	Distorted	459.10 FL	*459.10 FL
34	1		*REAR END PANEL INNER MEMBER	Distorted	186.90 FL	*186.90 FL
35	1		*REAR END PANEL TOP GARNISH	Deformed	216.70 FL	*216.70 FL
36	1		*TAILLAMP	N/S Smashed	733.00 FL	*366.50 FL
37	1		*TAILLAMP PANEL	N/S Dented	780.20 FL	*390.10 FL
38	1		*TAILGATE	Distorted	903.40 FL	*903.40 FL
39	1		*TAILGATE LOCK	Damaged	189.40 FL	*189.40 FL
40	1		*TAILGATE WEATHERSTRIPE	Cut	195.90 FL	*195.90 FL
41	2		*TAILGATE DAMPER	Not Necessary	424.20 FL	*- FL
42	1		*TAILGATE INNER TRIM BOARD	Cracked	285.10 FL	*285.10 FL
43	1		*TAILGATE OUTER GARNISH	Not Necessary	239.80 FL	*- FL
44	1		*TAILGATE WIPER MOTOR	Not Necessary	361.90 FL	*- FL
45	1		*TAILGATE WIPER ARM	Not Necessary	70.20 FL	*- FL
46	1		*TAILGATE GLASS MOULDING	Necessary	124.10 FL	*124.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*HONDA LOGO	Not Necessary	45.90 FL	*- FL
48	1		*STREAM WORDING	Necessary	49.10 FL	*49.10 FL
49	1		*FLOOR PANEL	Repair	1,062.70 FL	*- FL
50	1		*FLOOR PANEL TOP COVER	N/S Deformed	482.20 FL	*242.10 FL
51	1		*REAR FENDER	N/S Distorted	1,857.40 FL	*928.70 FL
52	1		*REAR FENDER INNER TRIM BOARD	N/S Deformed	590.80 FL	*295.40 FL
53	2		*REAR FENDER INNER SHIELD	Not Necessary	160.20 FL	*- FL
54	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
55	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
56	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
57	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
58	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*FRONT SUPPORT PANEL TOP COVER CLIPS	Not Necessary	20.00 FS	*- FS
60	1		*COOLANT	Not Necessary	50.00 FS	*- FS
61	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
62	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
63	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
64	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
65	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
66	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
67	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
68	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
69	1		*TAILGATE INNER SIDE GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
70	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
71	1		*FLOOR PANEL INSULATION PADS	Not Necessary	280.00 FS	*- FS
72	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
73	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
74	1		*REAR FENDER GLASS SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,794.30	8,075.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,086.86	1,511.00
Total Parts (\$\$)	17,707.44	6,564.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,400.00	1,600.00
2	SPRAY PAINTING	New	2,500.00	1,400.00
3	WIRING	New	100.00	60.00
4	TO APPLY TUFF COAT	New	150.00	100.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	New	120.00	0.00
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	New	120.00	0.00
8	TO REMOVE UPHOLSTERY	New	150.00	0.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE REVERSE SENSOR	New	100.00	50.00
12	TO REMOVE FUEL TANK	New	150.00	60.00
13	TO REMOVE FENDER GLASSES	New	240.00	40.00
Gross Labour Cost (S\$)			7,510.00	3,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >