

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS23000313/UQY3Q2**Date:** 03/02/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SMA9217Z **Insured Vehicle No :** SMN6035H

Date of Loss: 06/01/2023 Nature of Claim: TP Claim No: DMPC2300015H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA9217Z**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZ8534954

Reg. Date: 22/06/2018 (Man. Year: 2018) Chassis No: NHP1707125329

Colour: Blue Odometer: 128394 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 15,164.20         | 4,843.95          | 10,320.25         | 68.06         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 4,290.00          | 1,440.00          | 2,850.00          | 66.43         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>19,454.20</b>  | <b>6,283.95</b>   | <b>13,170.25</b>  | <b>67.70</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,000.00</b>   |                   |               |
| <b>(S\$)</b>                             | 19,454.20         | 5,000.00          | 14,454.20         | 74.30         |
| <b>+ GST 8.00/8.00% (S\$)</b>            | 1,556.34          | 400.00            | 1,156.34          | 74.30         |
| <b>Nett Amount (S\$)</b>                 | <b>21,010.54</b>  | <b>5,400.00</b>   | <b>15,610.54</b>  | <b>74.30</b>  |

INSPECTION

Date of Assignment: 10/01/2023

Date Inspected: 12/01/2023 Inspected At: Abwin Service Pte Ltd (HQ)  
17 Kaki Bukit Road 4, Bartley Biz Centre #01-58/59/60/61/62  
Singapore 417809

Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                         |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                         |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 02 Feb 2023)           |
| Parts:        | M1-MPV                                                                                                                                                                       | TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| Print Code:   | (Unsubmitted, no print-code for SMA9217Z)                                                                                                                                    |                                                         |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition        | Repairer's | Amount       |
|-----|-----|----------|----------------------------------|------------------|------------|--------------|
| 1   | 1   |          | *TAIL GATE                       | Badly Dented     | 1,356.60 F | *1,356.60 FL |
| 2   | 1   |          | *TAILGATE LOCK                   | Jammed / Damaged | 562.00 F   | *341.90 FL   |
| 3   | 1   |          | *TAILGATE CATCH                  | Twisted          | 31.00 F    | *31.00 FL    |
| 4   | 1   |          | *TAILGATE INNER TRIM             | Not Necessary    | 165.70 F   | *- FL        |
| 5   | 1   |          | *TAILGATE INNER TRIM HANDLE      | Not Necessary    | 28.20 F    | *- FL        |
| 6   | 1   |          | *TAILGATE HINGE RH               | Not Necessary    | 73.50 F    | *- FL        |
| 7   | 1   |          | *TAILGATE HINGE LH               | Not Necessary    | 73.50 F    | *- FL        |
| 8   | 1   |          | *TAILGATE DAMPER RH              | Not Necessary    | 291.10 F   | *- FL        |
| 9   | 1   |          | *TAILGATE DAMPER LH              | Not Necessary    | 291.10 F   | *- FL        |
| 10  | 1   |          | *TAILGATE WEATHERSTRIP           | Twisted          | 446.90 F   | *288.90 FL   |
| 11  | 1   |          | *TAIL LAMP LH                    | Cracked / Cut    | 439.60 F   | *439.60 FL   |
| 12  | 1   |          | *TAIL LAMP RH                    | Cracked          | 439.60 F   | *439.60 FL   |
| 13  | 1   |          | *TAILGATE LAMP RH                | Scratched        | 314.40 F   | *314.40 FL   |
| 14  | 1   |          | *TAILGATE LAMP LH                | Scratched        | 314.40 F   | *314.40 FL   |
| 15  | 1   |          | *REAR CORNER PANEL LH (NPA)      | Repair           | 0.00 F     | *- FL        |
| 16  | 1   |          | *REAR CORNER PANEL RH (NPA)      | Repair           | 0.00 F     | *- FL        |
| 17  | 1   |          | *REAR BUMPER                     | Cut / Warped     | 382.00 F   | *382.00 FL   |
| 18  | 1   |          | *REAR BUMPER OUTER GARNISH LH    | Not Necessary    | 154.60 F   | *- FL        |
| 19  | 1   |          | *REAR BUMPER OUTER GARNISH RH    | Not Necessary    | 154.60 F   | *- FL        |
| 20  | 1   |          | *REAR BUMPER CENTRE GARNISH      | Grazed           | 228.00 F   | *228.00 FL   |
| 21  | 1   |          | *REAR BUMPER REFLECTOR LH        | Not Necessary    | 72.20 F    | *- FL        |
| 22  | 1   |          | *REAR BUMPER REFLECTOR RH        | Not Necessary    | 72.20 F    | *- FL        |
| 23  | 1   |          | *REAR BUMPER SIDE RETAINER LH    | Not Necessary    | 120.70 F   | *- FL        |
| 24  | 1   |          | *REAR BUMPER SIDE RETAINER RH    | Not Necessary    | 120.70 F   | *- FL        |
| 25  | 1   |          | *REAR END PANEL OUTER            | Badly Dented     | 521.40 F   | *521.40 FL   |
| 26  | 1   |          | *REAR END PANEL INNER            | Repair           | 538.40 F   | *- FL        |
| 27  | 1   |          | *REAR END PANEL TOP GARNISH      | Twisted          | 176.50 F   | *176.50 FL   |
| 28  | 1   |          | *FLOOR PANEL (NPA)               | Not Necessary    | 0.00 F     | *- FL        |
| 29  | 1   |          | *REAR FENDER LH                  | Not Necessary    | 1,884.40 F | *- FL        |
| 30  | 1   |          | *REAR FENDER RH                  | Not Necessary    | 1,884.40 F | *- FL        |
| 31  | 1   |          | *TOOL BOX TOP BOARD              | Cracked          | 536.40 F   | *536.40 FL   |
| 32  | 1   |          | *TAILGATE EMBLEM (TOYOTA)        | Necessary        | 81.10 F    | *81.10 FL    |
| 33  | 1   |          | *TAILGATE WIPER                  | Not Necessary    | 123.70 F   | *- FL        |
| 34  | 1   |          | *TAILGATE WIPER MOTOR            | Bent / Jammed    | 925.10 F   | *705.10 FL   |
| 35  | 1   |          | *TAILGATE EMBLEM SIENTA          | Necessary        | 61.70 F    | *61.70 FL    |
| 36  | 1   |          | *REAR BUMPER DIFUSSER (NPA)      | No such part     | 0.00 F     | *- FL        |
| 37  | 1   |          | *REAR NUMBER PLATE WITH BRACKET  | Bent             | 40.00 FS   | *40.00 FS    |
| 38  | 10  |          | *REAR BUMPER CLIPS               | Necessary        | 50.00 FS   | *50.00 FS    |
| 39  | 1   |          | *TAILGATE SEALANT                | Not Necessary    | 50.00 FS   | *- FS        |
| 40  | 1   |          | *WINDSCREEN SEALANT              | Necessary        | 120.00 FS  | *40.00 FS    |
| 41  | 1   |          | *END PANEL SEALANT               | Necessary        | 50.00 FS   | *50.00 FS    |
| 42  | 2   |          | *REAR BUMPER SENSOR              | Not Necessary    | 720.00 FS  | *- FS        |
| 43  | 1   |          | *REVERSE CAMERA                  | Not Necessary    | 380.00 FS  | *- FS        |
| 44  | 10  |          | *REAR END PANEL TOP GARNISH CLIP | Not Necessary    | 50.00 FS   | *- FS        |
| 45  | 1   |          | *SPARE TYRE PANEL                | Not Necessary    | 838.50 FS  | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

2/3/23, 12:08 PM

Adjuster Report

| No.                                              | Qty | Part No. | Particulars | Condition | Repairer's | Amount    |
|--------------------------------------------------|-----|----------|-------------|-----------|------------|-----------|
| Sub Total (\$)                                   |     |          |             |           |            | 15,164.20 |
| - List Item Discount on L Items 0.00/25.00% (\$) |     |          |             |           |            | 0.00      |
| Total Parts (\$)                                 |     |          |             |           |            | 15,164.20 |
| 6,398.60                                         |     |          |             |           |            | 1,554.65  |
| 4,843.95                                         |     |          |             |           |            |           |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                     | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                 |          |                 |                 |
| 1                               | TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS  | New      | 1,800.00        | 580.00          |
| 2                               | TO SPRAY PAINT ON AFFECTED AREAS                                | New      | 1,800.00        | 600.00          |
| 3                               | TO APPLY UNDERCOATING FOR RUST PROOFING                         | New      | 120.00          | 30.00           |
| 4                               | TO REMOVE AND REFIX REAR WINDSCREEN                             | New      | 120.00          | 120.00          |
| 5                               | TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE SENSOR & TESTING } | New      | 100.00          | 50.00           |
| 6                               | TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE CAMERA & TESTING } | New      | 100.00          | 0.00            |
| 7                               | TO DISMANTLE & REFIX INTERIOR UPHOLSTERY                        | New      | 250.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                 |          | <b>4,290.00</b> | <b>1,440.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >