

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 31 Jan 2023

**Preliminary Advice**

Insured Vehicle No	: SMN6035H	Accident Date	: 06/01/2023
TP Vehicle No	: SMA9217Z	Assignment Date	: 10/01/2023
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 6
Date of Inspection	: 12/01/2023		
Inspection At	: ABWIN SERVICE PTE LTD (HQ) 17 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE #01-58/59/60/61/62 SINGAPORE 417809		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,364.20
Revised Amount	:S\$	6,283.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,283.95

Lump Sum Repair	:S\$	5,000.00
-----------------	------	----------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.