

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/1523000313/U943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SMA92177

Yr Regn:

22/06/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / Hybrid

Make:

Toyota Sienna

c.c

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

128394

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

06/01/23

D.O.I.

12/1/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 30/1/23

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

MER TP

Lump Sum / I.B.K. (\$

5000

30/1/23 4/5 \$5000 insured with Buo. CRed \$14364.20, 74%

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
Service Pte Ltd**M9 Automobile Pte Ltd****M9 International Pte Ltd***NOT AUTHORIZED**LEK**12/1/23**1/5 \$5000 / 6 days***QUOTATION: HQQ000719****SMA9217Z****YEE ZHENYANG**

89 PASIR RIS HEIGHTS 12-

13

SINGAPORE 519286

CONTACT NO : 83669957

DATE	:	11-JAN-2023
PAYMENT TERMS	:	0 DAYS
VALIDITY	:	
MAKE	:	TOYOTA
MODEL	:	SIENTA HYBRID 1.5G CVT
CHASSIS NO	:	NHP1707125329
ENGINE NO	:	1NZ8534954
MILEAGE	:	0 KM
SERVICE ADVISOR	:	SHERELL
PAGE	:	1 OF 3

NO	DESCRIPTION	QTY	UNIT PRICE	SUM (SGD)
1	TAIL GATE <i>Body</i>	1	1,356.60	1,356.60
2	TAILGATE LOCK <i>1m/dye</i>	1	562.00	562.00
3	TAILGATE CATCH <i>Tw</i>	1	31.00	31.00
4	TAILEGATE INNER TRIM <i>11</i>	1	165.70	165.70
5	TAILGATE INNER TRIM HANDLE <i>11</i>	1	28.20	28.20
6	TAILGATE HINGE RH <i>11</i>	1	73.50	73.50
7	TAILGATE HINGE LH <i>11</i>	1	73.50	73.50
8	TAILGATE DAMPER RH <i>11</i>	1	291.10	291.10
9	TAILGATE DAMPER LH <i>11</i>	1	291.10	291.10
10	TAILGATE WEATHER STRIP <i>Tw</i>	1	446.90	446.90
11	TAIL LAMP LH <i>one/cut</i>	1	439.60	439.60
12	TAIL LAMP RH <i>one</i>	1	439.60	439.60
13	TAILGATE LAMP RH <i>scn</i>	1	314.40	314.40
14	TAILGATE LAMP LH <i>scn</i>	1	314.40	314.40
15	REAR CORNER PANEL LH <i>1</i>	1	0.00	0.00
16	REAR CORNER PANEL RH <i>1</i>	1	0.00	0.00
17	REAR BUMPER <i>cut/wash</i>	1	382.00	382.00
18	REAR BUMPER OUTER GARNISH LH <i>11</i>	1	154.60	154.60
19	REAR BUMPER OUTER GARNISH RH <i>11</i>	1	154.60	154.60
20	REAR BUMPER CENTRE GARNISH <i>grout</i>	1	228.00	228.00
21	REAR BUMPER REFLECTOR LH <i>11</i>	1	72.20	72.20
22	REAR BUMPER REFLECTOR RH <i>11</i>	1	72.20	72.20
23	REAR BUMPER SIDE RETAINER LH <i>11</i>	1	120.70	120.70
24	REAR BUMPER SIDE RETAINER RH <i>11</i>	1	120.70	120.70
25	REAR END PANEL OUTER <i>Body</i>	1	521.40	521.40
26	REAR END PANEL INNER <i>1</i>	1	538.40	538.40
27	REAR END PANEL TOP GARNISH <i>Tw</i>	1	176.50	176.50
28	FLOOR PANEL <i>11</i>	1	0.00	0.00

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
Service Pte Ltd**M9 Automobile Pte Ltd**
M9 International Pte Ltd**QUOTATION: HQQ000719****SMA9217Z****YEE ZHENYANG**

89 PASIR RIS HEIGHTS 12-

13

SINGAPORE 519286

CONTACT NO : 83669957

DATE	:	11-JAN-2023
PAYMENT TERMS	:	0 DAYS
VALIDITY	:	
MAKE	:	TOYOTA
MODEL	:	SIENTA HYBRID 1.5G CVT
CHASSIS NO	:	NHP1707125329
ENGINE NO	:	1NZ8534954
MILEAGE	:	0 KM
SERVICE ADVISOR	:	SHERELL
PAGE	:	2 OF 3

NO	DESCRIPTION	QTY	UNIT PRICE	SUM (SGD)
29	REAR FENDER LH 11	1	1,884.40	1,884.40 X
30	REAR FENDER RH 11	1	1,884.40	1,884.40 X
31	TOOL BOX TOP BOARD 11	1	536.40	536.40 /
32	TAILGATE EMBLEM (TOYOTA) 11	1	81.10	81.10 /
33	TAILGATE WIPER 11	1	123.70	123.70 X
34	TAILGATE WIPER MOTOR 11	1	925.10	925.10 /
35	TAILGATE EMBLEM "SIENTA" 11	1	61.70	61.70 /
36	REAR BUMPER DIFUSSER 11	1	0.00	0.00 X
37	REAR NUMBER PLATE WITH BRACKET 11	1	0.00	0.00 /
38	REAR BUMPER CLIPS 11	10	5.00	50.00 /
39	TAILGATE SEALANT 11	1	50.00	50.00 X
40	WINDSCREEN SEALANT 11	1	120.00	120.00 /
41	END PANEL SEALANT 11	1	0.00	0.00 /
42	REAR BUMPER SENSOR 11	2	360.00	720.00 X
43	REVERSE CAMERA 11	1	380.00	380.00 X
44	REAR END PANEL TOP GARNISH CLIP 11	10	5.00	50.00 X
45	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1	1,800.00	1,800.00 580
46	TO SPRAY PAINT ON AFFECTED AREAS	1	1,800.00	1,800.00 600
47	TO APPLY UNDERCOATING FOR RUST PROOFING	1	120.00	120.00 30
48	TO REMOVE AND REFIX REAR WINDSCREEN	1	120.00	120.00 120

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN
Service Pte Ltd**M9 Automobile Pte Ltd**
M9 International Pte Ltd**QUOTATION: HQQ000719**

SMA9217Z
YEE ZHENYANG
89 PASIR RIS HEIGHTS 12-
13
SINGAPORE 519286
CONTACT NO : 83669957

DATE : 11-JAN-2023
PAYMENT TERMS : 0 DAYS
VALIDITY :
MAKE : TOYOTA
MODEL : SIENTA HYBRID 1.5G CVT
CHASSIS NO : NHP1707125329
ENGINE NO : 1NZ8534954
MILEAGE : 0 KM
SERVICE ADVISOR : SHERELL
PAGE : 3 OF 3

NO	DESCRIPTION	QTY	UNIT PRICE	SUM (SGD)
49	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	1	100.00	100.00
50	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	1	100.00	100.00
51	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	1	250.00	250.00
52	SPARE TYRE PANEL	1	838.50	838.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SGD : TWENTY THOUSAND NINE HUNDRED AND THIRTEEN AND THIRTY-FOUR CENTS
ONLY

SUB-TOTAL : 19,364.20

GST - 8 % : 1,549.14

TOTAL : 20,913.34

ABWIN SERVICE PTE LTD**Confirmed & Accepted**

Prepared By

Signature & Company's Stamp