

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000316/KNP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00074482200
Claimant Vehicle No :	SME162K	Insured Vehicle No :	SJN8309R
Date of Loss:	06/01/2023	Nature of Claim: TP	Claim No: SNM23D200187/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME162K	Engine No:	16305367B58B30A
Make & Model:	BMW M240I, 3.0 LED NAV (A)	Chassis No:	WBA2J52040VD72525
Reg. Date:	14/09/2018 (Man. Year: 2018)	Odometer:	68012 km
Colour:	Metallic Blue		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	245/35 R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,220.50	15,760.26	4,460.24	22.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,310.00	2,590.00	3,720.00	58.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,530.50	18,350.26	8,180.24	30.83
Approved Total (Overridden) (S\$)		14,600.00		
Nett Amount (S\$)	26,530.50	14,600.00	11,930.50	44.97

INSPECTION

Date of Assignment:	09/01/2023	Ching Motor Repair Shop (HQ)
Date Inspected:	10/01/2023 Inspected At:	BLK 176 SIN MING DRIVE, #02-08 SIN MING AUTOCARE
Estimated Period of Repair:	9.0 days	Singapore 575721

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	BMW M240I 3.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME162K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,281.20 F	*1,281.20 FL
2	2		*REAR BOOT HINGE (LEFT & RIGHT)	Repair	151.20 F	*- FL
3	1		*REAR BOOT WEATHERSTRIP	Distorted / Dented	141.50 F	*141.50 FL
4	1		*REAR BOOT LOCK	Dented	205.40 F	*205.40 FL
5	1		*REAR BOOT LOCK STRIKER	Repair	67.95 F	*- FL
6	1		*REAR BOOT INSULATOR (NPA)	Serviceable	0.00 F	*- FL
7	1		*REAR BOOT INNER TOP BOARD COVER	Serviceable	92.70 F	*- FL
8	1		*REAR BOOT TOP SPOILER	Serviceable	758.55 F	*- FL
9	1		*BMW EMBLEM	Necessary	92.95 F	*92.95 FL
10	1		*M24DIEMBLEM	Necessary	103.80 F	*103.80 FL
11	2		*TAIL LAMP (LEFT & RIGHT)	Cracked	1,137.60 F	*1,137.60 FL
12	1		*REAR BUMPER	Bent	1,141.65 F	*1,141.65 FL
13	10		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
14	1		*REAR BUMPER SPONGE	Serviceable	168.00 F	*- FL
15	2		*REAR BUMPER STAY (LEFT & RIGHT)	Repair	256.00 F	*- FL
16	2		*REAR BUMPER SIDE RETAINER (LEFT & RIGHT)	Distorted	311.60 F	*311.60 FL
17	2		*REAR BUMPER REVERSE SENSOR	Shorted	551.90 F	*551.90 FL
18	1		*REAR BUMPER LOWER LIP	Bent	283.45 F	*283.45 FL
19	1		*REAR BUMPER TOW COVER	Missing	55.95 F	*55.95 FL
20	2		*REAR BUMPER LAMP (LEFT & RIGHT)	N/S Cracked / O/S Distorted	98.00 F	*98.00 FL
21	1		*REAR BUMPER INNER BEAM	Broken	467.85 F	*467.85 FL
22	1		*REAR BUMPER UPPER GUIDE	Serviceable	179.90 F	*- FL
23	1		*REAR BUMPER LOWER GUIDE	Serviceable	199.50 F	*- FL
24	1		*REAR END PANEL	Bent	552.40 F	*552.40 FL
25	1		*REAR END PANEL TOP GARNISH	Dented	112.50 F	*112.50 FL
26	8		*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 F	*40.00 FL
27	1		*REAR SPARE TYRE TANK PANEL	Repair	495.50 F	*- FL
28	1		*REAR SPARE TYRE PANEL COVER BOARD	Serviceable	85.70 F	*- FL
29	2		*REAR SPARE TYRE PANEL HEAT SHIELD (LEFT & RIGHT)	Bent	165.40 F	*165.40 FL
30	1		*REAR NUMBER PLATE WITH CASING	Serviceable	95.00 F	*- FL
31	2		*REAR EXHAUST BOX	Bent	1,287.80 F	*1,287.80 FL
32	2		*REAR EXHAUST PIPE	Bent	1,230.50 F	*1,230.50 FL
33	1		*KEYLESS SENSOR	Dented	168.00 F	*168.00 FL
34	1		*KEYLESS KICK MODULE	Mtg Cracked	595.00 F	*595.00 FL
35	1		*FRONT BUMPER	Buckled	1,274.35 F	*1,274.35 FL
36	1		*FRONT BUMPER SPONGE	Serviceable	97.45 F	*- FL
37	1		*FRONT BUMPER REINFORCEMENT	Bent	423.70 F	*423.70 FL
38	2		*FRONT BUMPER BRACKET (LH & RH)	Repair	247.60 F	*- FL
39	2		*FRONT BUMPER SIDE RETAINER (LH & RH)	Serviceable	133.10 F	*- FL
40	2		*FRONT BUMPER CENTRE CHROME GRILLE	Cracked	132.50 F	*132.50 FL
41	1		*FRONT BUMPER TOW COVER	Serviceable	55.70 F	*- FL
42	1		*FRONT BUMPER BMW LOGO	Necessary	82.85 F	*82.85 FL
43	2		*FRONT BUMPER SENSOR	Serviceable	551.90 F	*- FL
44	1		*FRONT NUMBER PLATE WITH CASING	Bent	95.00 FS	*95.00 FS
Report was unsubmitted during this print-out.						

5/15/23, 4:06 PMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*FRONT HEAD LAMP (LH & RH)	Mtg Cracked	4,521.90 F	*4,521.90 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	20,220.50
					- List Item Discount on L Items 0.00/5.00% (\$)	0.00
					Total Parts (\$)	20,220.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEATING ON ALL ACCIDENT AFFECTED PARTS ,JACKING FRONT BONNET ,JACKING REAR TWO SIDE FENDER ,CUTTING REAR END PANEL ,REAR SPARE TYRE TANK PANEL ,DISMANTLE & REPLACE THE ABOVE FRONT AND REAR MENTIONED PARTS	New	2,500.00	1,000.00
2	LABOUR FOR RESPRAY FRONT BONNET ,FRONT BUMPER,REAR END PANEL ,REAR BUMPER, REAR SPARE TYRE TANK PANEL ,REAR BOOT LID ,REAR LEFT & RIGHT SIDE FENDER	New	2,400.00	1,250.00
3	COMPUTER CODING OF FRONT TWO HEAD LAMP ,ELECTRICAL WIRING INCLUDING & FOCUSING ADJUSTMENT	New	300.00	30.00
4	SCANNING AND DIAGNOSE OF COMPUTER FOR FRONT TWO SIDE HEAD LAMP	New	250.00	120.00
5	PROGRAM AND RESET THE WHOLE ELECTRICAL & ELECTROLNIC SYSTEM	New	500.00	0.00
6	TO PERFORM WATER LEAKAGE TEST	New	80.00	30.00
7	TO TESTING AND REPLACE FRONT & REAR REVERSE SENSOR	New	80.00	80.00
8	LABOUR FOR DISMANTLE & REPLACE REAR EXHAUST	New	200.00	80.00
Gross Labour Cost (S\$)			6,310.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >