

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG23000318/UYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220109747
Claimant Vehicle No :	SLM9836K	Insured Vehicle No :	SMV6796C
Date of Loss:	07/01/2023	Nature of Claim:	TP
		Claim No:	5475020786SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9836K		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZ317364
Reg. Date:	19/04/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V8H1058037
Colour:	Red	Odometer:	68231 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,123.07	1,545.12	6,577.95	80.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,849.00	400.00	2,449.00	85.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,972.07	1,945.12	9,026.95	82.27
Approved Total (Overridden) (\$\$)		1,500.00		
Nett Amount (\$\$)	10,972.07	1,500.00	9,472.07	86.33
+ Loss of Use (2.0 x S\$60.00/day) (\$\$)		120.00		
+ Doc/Search Fee (\$\$)		26.75		
Nett Liability (\$\$)		1,646.75		

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	10/01/2023	Inspected At:	SPEEDWERKZ PTE LTD (HQ) 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE ASSY	Not Necessary	1,323.50 FL	*- FL
2	1		*FRONT BUMPER	Dented / Deformed	2,381.30 FL	*1,716.80 FL
3	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	65.80 FL	*- FL
4	1		*FRONT BUMPER TOWING COVER	Not Necessary	41.60 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	144.90 FL	*- FL
6	1		*FRONT BUMPER WATER JET	Not Necessary	225.40 FL	*- FL
7	1		*FRONT BUMPER WATER JET COVER	Not Necessary	51.30 FL	*- FL
8	1		*FRONT BUMPER WATER JET HOSE	Not Necessary	45.70 FL	*- FL
9	2		*FRONT FOG LAMP	Not Necessary	482.00 FL	*- FL
10	1		*FRONT HEAD LAMP	Not Necessary	2,186.60 FL	*- FL
11	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	113.80 FL	*- FL
12	1		*FRONT FENDER	Not Necessary	1,231.20 FL	*- FL
13	1		*FRONT FENDER COWLING	Not Necessary	257.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,550.60	1,716.80
- List Item Discount on L Items 5.00/10.00% (\$)	427.53	171.68
Total Parts (\$)	8,123.07	1,545.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	350.00	0.00
2	TO REMOVE AND REPLACE SPARE PARTS	New	1,299.00	200.00
3	TO SPRAY PAINTING	New	1,200.00	200.00
Gross Labour Cost (S\$)			2,849.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >