

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000319/UQP3E2**Date:** 18/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00253942101

**Claimant Vehicle
No :** SLP277S**Insured Vehicle
No :** SMY1691M

Date of Loss: 29/12/2022

Nature of Claim: TP

Claim
No: SNM23D200002/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP277S**

Make & Model: MAZDA 3, 1.6 (A)

Engine No: P520442618

Reg. Date: 24/05/2017 (Man. Year: 2017)

Chassis No: JM6BN22A8H0151320

Colour: Silver

Odometer: 320979 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: LANVIGATOR 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,452.24	2,506.80	7,945.44	76.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	750.00	2,470.00	76.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,672.24	3,256.80	10,415.44	76.18
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	13,672.24	2,600.00	11,072.24	80.98

INSPECTION

Date of Assignment: 10/01/2023

Date Inspected: 10/01/2023 Inspected At:

2ND Auto Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre
Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP277S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted / Torn	1,282.00 FL	*1,083.30 FL
2	1		*FRONT BUMPER SIDE RETAINERS	O/S Cracked	224.00 FL	*45.00 FL
3	2		*FRONT BUMPER DAYLIGHT W/COVER (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*FRONT BUMPER CENTRE GRILLE (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*FRONT CENTRE GRILLE (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	62.00 FL	*- FL
7	1		*RHS HEADLAMP	Scratched / Cracked	1,182.00 FL	*1,182.00 FL
8	1		*RHS HEADLAMP BRACKET	Not Necessary	98.00 FL	*- FL
9	1		*FRONT BONNET	Not Necessary	1,452.00 FL	*- FL
10	2		*FRONT BONNET HINGE	Not Necessary	116.00 FL	*- FL
11	1		*FRONT BONNET INNER RUBBER STRIP	Not Necessary	75.00 FL	*- FL
12	2		*FRONT BONNET RUBBER STOPPER	Not Necessary	48.00 FL	*- FL
13	1		*RHS FRONT FENDER	Bent	982.00 FL	*350.60 FL
14	1		*RHS FRONT FENDER TOP SIDE GARNISH	Not Necessary	230.00 FL	*- FL
15	1		*RHS FRONT FENDER INNER SIHELD	Deformed / Torn	318.20 FL	*165.00 FL
16	1		*RHS SIDE ROOF OUTER PANEL (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*RHS FRONT DOOR	Not Necessary	1,120.00 FL	*- FL
18	1		*RHS FRONT DOOR UPPER MOULDING	Not Necessary	112.00 FL	*- FL
19	1		*RHS FRONT DOOR GLASS CHANNEL	Not Necessary	102.00 FL	*- FL
20	1		*RHS FRONT DOOR LOWER MOULDING	Not Necessary	124.00 FL	*- FL
21	1		*RHS FRONT DOOR SIDE BLACK TAPE	Not Necessary	72.00 FL	*- FL
22	1		*RHS FRONT DOOR HINGES	Not Necessary	98.00 FL	*- FL
23	1		*RHS FRONT DOOR INNER LOCK	Not Necessary	282.00 FL	*- FL
24	1		*RHS FRONT DOOR INNER TRIM BOARD (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*RHS FRONT DOOR OUTER HANDLE (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*RHS SIDE VIEW MIRROR ASSY	Not Necessary	672.00 FL	*- FL
27	1		*RHS SIDE SILL (ROCKER PANEL)	Not Necessary	980.00 FL	*- FL
28	1		*RHS FRONT SHOCK ABSORBER	Not Necessary	592.00 FL	*- FL
29	1		*RHS FRONT LOWER ARM	Not Necessary	382.00 FL	*- FL
30	1		*RHS FRONT KNUCKLE ARM	Not Necessary	492.00 FL	*- FL
31	1		*RHS FRONT KNUCKLE ARM BEARING	Not Necessary	298.00 FL	*- FL
32	1		*RHS FRONT WASHER TANK	Deformed	195.10 FL	*195.10 FL
33	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
34	1		*RHS FRONT SPORTS RIM	Not Necessary	980.00 FS	*- FS
35	1		*SET RHS FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*40.00 FS
36	1		*SET RHS FRONT DOOR INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,770.30	3,111.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,318.06	604.20
Total Parts (\$\$)	10,452.24	2,506.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE THE DAMAGED PARTS	New	1,400.00	300.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,200.00	400.00
3	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT TEST	New	100.00	0.00
4	TO REMOVE AND REPLACE RHS FRONT UNDERCARRIAGE PARTS & SUSPENSION SYSTEM	New	250.00	0.00
5	TO REMOVE, CHECK AND REFIX WIRINGS AT FRONT DAMAGED AREAS AND FOCUS HEADLAMP BEAM	New	150.00	20.00
6	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (S\$)			3,220.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >