

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000323/UPA3Q2**Date:** 12/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700078450
Claimant Vehicle No :	SLJ2959B	Insured Vehicle No :	GBD4844K
Date of Loss:	09/01/2023	Nature of Claim:	TP
		Claim No:	7235372825SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2959B	Engine No:	2ZR1846626
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W30J005665
Reg. Date:	02/12/2016 (Man. Year: 2016)	Odometer:	213041 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Tourador 7 mm	Rear Left Side:	Tourador 7 mm
Front Right Side:	Tourador 7 mm	Rear Right Side:	Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,497.84	5,734.70	5,763.14	50.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,490.00	1,330.00	34.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,317.84	8,224.70	7,093.14	46.31
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	15,317.84	6,500.00	8,817.84	57.57
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		7,366.75		

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	10/01/2023	Inspected At:	Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390 Singapore 408700
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Baldy Dented	1,599.30 FL	*1,599.30 FL
2	1		*TAIL GATE EMBLEM	Necessary	67.70 FL	*67.70 FL
3	2		*TAIL GATE WINDSCREEN SIDE RUBBER	Necessary	75.60 FL	*75.60 FL
4	1		*TAIL GATE WINDSCREEN INNER SEALANT	Necessary	112.00 FS	*40.00 FS
5	1		*SET TAIL GATE WINDSCREEN TAPE FOAM	Necessary	52.16 FS	*30.00 FS
6	1		*TAIL GATE VALVE MATIC PLATE	Necessary	44.40 FS	*40.00 FS
7	1		*TAIL GATE RUBBER	Twisted	363.60 FL	*363.60 FL
8	2		*TAIL GATE DAMPER	Not Necessary	432.00 FL	*- FL
9	2		*TAIL GATE REFLECTOR	Cracked	636.40 FL	*636.40 FL
10	1		*TAIL GATE TOP LOCK	Dented / Jammed	446.30 FL	*446.30 FL
11	1		*TAIL GATE LOWER LOCK CATCH	Not Necessary	44.30 FL	*- FL
12	1		*TAIL CENTRE LOCK SWITCH	Cracked	193.90 FL	*193.90 FL
13	1		*TAIL GATE CENTRE CHROME	Cracked	368.00 FL	*368.00 FL
14	1		*TAIL GATE TRIM COVER GARNISH	Deformed / Torn	393.20 FL	*393.20 FL
15	2		*REAR FENDER SIDE TRIM COVER	Deformed / Twisted	804.00 FL	*804.00 FL
16	1		*TAIL GATE WIPER MOTOR	Bent / Jammed	398.20 FL	*398.20 FL
17	2		*TAIL LAMP	Not Necessary	767.20 FL	*- FL
18	2		*TAIL LAMP INNER PANEL	Repair	430.00 FL	*- FL
19	1		*REAR PANEL	Badly Dented	580.80 FL	*580.80 FL
20	1		*REAR PANEL LOWER LOCK CATCH COVER	Twisted	198.50 FL	*198.50 FL
21	1		*REAR BUMPER	Distorted	693.70 FL	*693.70 FL
22	1		*SET REAR BUMPER REVERSE SENSORS	Shorted	280.00 FS	*200.00 FS
23	2		*REAR BUMPER INNER BRACKET	Not Necessary	136.60 FL	*- FL
24	2		*REAR BUMPER TOP SIDE CLIP	Not Necessary	24.00 FL	*- FL
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
26	2		*REAR BUMPER SIDE HOLDER	Bent	211.00 FL	*211.00 FL
27	1		*REAR EXHAUST PIPE	Repair	1,295.90 FL	*- FL
28	2		*REAR FENDERS	Repair	2,317.00 FL	*- FL
29	2		*REAR BUMPER SIDE RETAINER	Bent	99.40 FL	*99.40 FL
30	2		*REAR BUMPER INNER LOWER BRACKET	Not Necessary	30.00 FL	*- FL
31	1		*REAR NUMBER PLATE WITH COVER	Bent	100.00 FS	*40.00 FS
32	1		*REAR SPARE PANEL	Repair	980.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,225.16	7,529.60
- List Item Discount on L Items 20.00/25.00% (\$\$)	2,727.32	1,794.90
Total Parts (\$\$)	11,497.84	5,734.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUSTPROOF	New	200.00	60.00
2	TO REMOVE / REFIT REAR WINDSCREEN	New	140.00	120.00
3	TO REMOVE / REFIT REAR INTERIOR TO EFFECT REPAIR	New	100.00	80.00
4	TO DISMANTLE / RENEW TAIL GATE	New	150.00	60.00
5	TO CHECK WIRING	New	50.00	20.00
6	TO DISMANTLE / RENEW REVERSE SENSORS	New	80.00	50.00
7	TO REMOVE / REFIT TOP SPOILER	New	100.00	0.00
8	TO DISMANTLE / RENEW ACCIDENT PORTION	New	1,500.00	1,000.00
9	TO SPRAY PAINT	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			3,820.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >